

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*

FORM APPROVED  
OMB NO. 1004-0135  
Expires: November 30, 2000

<b>SUBMIT IN TRIPLICATE - Other instructions on reverse side.</b>		5. Lease Serial No. <b>CONTRACT 108</b>
1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		6. If Indian, Allottee or Tribe Name
2. Name of Operator <b>AMOCO PRODUCTION COMPANY</b>	Contact: <b>CHERRY HLAVA</b> E-Mail: <b>hlavac@bp.com</b>	7. If Unit or CA/Agreement, Name and/or No.
3a. Address <b>P.O. BOX 3092 HOUSTON, TX 77253</b>	3b. Phone No. (include area code) Ph: <b>281.366.4081</b> Fx: <b>281.366.0700</b>	8. Well Name and No. <b>JICARILLA C 4E</b>
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) <b>Sec 24 T26N R5W Mer SWSW 790FSL 990FWL</b>		9. API Well No. <b>30-039-22298</b>
		10. Field and Pool, or Exploratory <b>BASIN DAKOTA</b>
		11. County or Parish, and State <b>RIO ARRIBA COUNTY, NM</b>

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA


TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

In response to your attached letter dated May 17, 2001, Amoco Production Company requests permission to perform repair work on the subject well, in the existing Basin Dakota field as per the attached procedure.

14. I hereby certify that the foregoing is true and correct. <b>Electronic Submission #5347 verified by the BLM Well Information System For AMOCO PRODUCTION COMPANY, sent to the Rio Puerco Committed to AFMSS for processing by Angie Medina-Jones on 06/29/2001 ()</b>	
Name (Printed/Typed) <b>CHERRY HLAVA</b>	Title <b>AUTHORIZED REPRESENTATIVE</b>
Signature	Date <b>06/28/2001</b>

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved By 	Lands and Mineral Resources Title	Date <b>7/1/01</b>
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**\*\* ORIGINAL \*\* ORIGINAL \*\* ORIGINAL \*\* ORIGINAL \*\* ORIGINAL \*\* ORIGINAL \*\* ORIGINAL \*\***

Jicarilla C 4E  
Basin Dakota  
API 30-039-222980  
Unit M Sec 24 T26N-R5W  
Rio Arriba County, NM

Procedure:

1. MIRU SU. Record TP and CP. Lay down well with clean 2% KCl water. Use absolute minimum of water possible to avoid formation damage. ND tree, NU BOP.
2. Tag for fill. POOH tallying tbg, visually inspecting.
3. RIH rabbiting following production string:
  - a) 1 jt 2-3/8" tbg
  - b) F-nipple w/ blanking plug
  - c) 2-3/8" tbg to surface
4. Land tbg at +/- 7450'. ND BOP, NU tree.
5. Load tubing with clean 2% KCl water. Test tubing to 500 psi. Swab tubing dry.
6. RU slickline. Make 1.906" gauge ring run. Retrieve plug.
7. Set FB stop and bumper spring.
8. Flow well for 2-3 hours, swabbing if necessary.
9. RDMO SU.

Allen Kutch

281-366-7955 office  
281-366-0700 fax  
888-788-6522 pager