

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		2. NAME OF OPERATOR Union Texas Petroleum		3. ADDRESS OF OPERATOR 375 U.S. Highway 64, Farmington, New Mexico 87401		4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 800' FNL & 800' FEL		5. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6639' G.L.		6. LEASE DESIGNATION AND SERIAL NO. Jicarilla Contract 153		7. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache		7. UNIT AGREEMENT NAME N/A		8. FARM OR LEASE NAME JICARILLA J		9. WELL NO. 23		10. FIELD AND POOL, OR WILDCAT Blanco MV/ West Lindrith Gal-Dk		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 25-T26N-R5W		12. COUNTY OR PARISH Rio Arriba		13. STATE NM	
--	--	--	--	---	--	--	--	---------------	--	--	--	---	--	--	--	-------------------------------	--	--------------------------------------	--	-------------------	--	--	--	--	--	------------------------------------	--	-----------------	--

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>	(Other)	<input type="checkbox"/>		
(Other) Recomplete and commingle <input checked="" type="checkbox"/>				(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Union Texas Petroleum desires to recomplete this well in the Gallup formation of the West Lindrith Gallup-Dakota pool and commingle with the Blanco Mesaverde. The commingling will be pursuant to NMOCD Order No: R-7507 dated April 20, 1984. The commingling will be completed as follows:

1. Set BP at 7100'+ isolating Dakota zone.
2. Run GR-CCL-CBL over Gallup interval. Squeeze if necessary.
3. Perforate Gallup with 1 SPF at 6488', 90', 95', 6504', 6519', 20', 21', 28', 29', 30', 56', 58', 72', 74', 97', 6612', 14', 33', 38', 40', 42', 46', 48', 52', 55', 57', 62', 68', 74', 76', 80', 86', 88', 6702', 28', 36', 50', 60', 87', 6945', 46', 47', 48'.
4. Acidize with 2400 gals 15% HCl and 86 - 7/8" ball sealers.
5. Frac with 100,000# 20/40 sand in 76,000 gals 20# x-linked gelled water.
6. Drill out BP.
7. Clean up well.
8. Run 2-3/8", 4.7# tubing to 7300'+.
9. Resume production.

18. I hereby certify that the foregoing is true and correct.

SIGNED Robert L. Frank TITLE Permit Coordinator

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

APPROVED

DATE 06/23/1987

JUN 26 1987

DATE

AREA MANAGER  
FARMINGTON RESOURCE AREA

\*See Instructions on Reverse Side

NMOCC