



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

GARREY CARRUTHERS
GOVERNOR

October 19, 1987

Ms. Barbara Norman
Union Texas Petroleum Corp.
375 US Highway 64
Farmington, NM 87401

Re: Jicarilla G #8 G-02-26N-5W
Jicarilla J #23 A-25-26N-5W

Dear Barbara:

Annual packer leakage tests on the referenced wells were inconclusive in proving zone separation.

Please reschedule and retest the wells in such a manner as to prove zone separation. Shut in both zones for a minimum of 3 days. Blow the higher pressured zone to the atmosphere or through a separator for as long as it takes to get a significant pressure drop.

Please notify this office at least 24 hours prior to tests, so we may provide a witness.

Yours truly,

Charles Gholson
Deputy Oil & Gas Inspector

CG/dj

xc: ~~W&A~~ Files