



BRUCE KING
GOVERNOR


STATE OF NEW MEXICO

ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

ANITA LOCKWOOD
CABINET SECRETARY

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178



November 2, 1992

MS SUSAN DOLAN
MERIDIAN OIL INC
PO BOX 4289
FARMINGTON NM 87499

RE: Meridian Oil Inc: Jicarilla West #9, K-06-26N-05W
Jicarilla J #10E, N-26-26N-05W
Jicarilla J #23, A-25-26N-05W

Southland Royalty Co: Burnt Mesa #1A, J-25-32N-07W
Reese Mesa #6, J-10-32N-08W

Dear Susan:

The 1992 Packer tests on the referenced wells indicate communication between the producible zones. In order to comply with Rule 112A, you are hereby directed to initiate immediate remedial activity. The Jicarilla J #23 has been leaking since 1991.

Yours Truly,

Charles Gholson
Deputy Oil & Gas Inspector

CG/sh