Form approved. Budget Bureau No. 1004-0135 UNITED STATES SUBMIT IN TRIPLICATES Form 3160-5 (November 1983) DEPARTMENT OF THE INTERIOR verse side) Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. (Formerly 9-331) BUREAU OF LAND MANAGEMENT Jicarilla Contract 153 RECEIVEN 6. IE INDIAN, ALLOTTES OR TRIBS NAME SUNDRY NOTICES AND REPORTS ON BIMEMAIL ROOM (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT" for such proposals.) "I(I) 24 AM 10: 43 Jicarilla Apache FARMINGTON RESOURCE AREA FARMINGTON, NEW MEXICO OIL GAS XX OTHER 8. PARM OR LEASE HAME NAME OF OPERATOR JICARILLA J Union Texas Petroleum 9. WELL NO. 3. ADDRESS OF OPERATOR 375 U.S. Highway 64, Farmington, New Mexico 87401

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*
See also space 17 below.)

At surface Blanco MV/ West Lindrith Gal/DK 11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA 940' FNL & 1100' FEL Section 36-T26N-R5W 12. COUNTY OR PARISH 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. NM 6663' G.L. Rio Arriba Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16. REPAIRING WELL WATER SHUT-OFF PULL OR ALTER CASING TEST WATER SHUT-OFF FRACTURE TREATMENT ALTERING CASING MULTIPLE COMPLETE PRACTURE TREAT SHOOTING OR ACIDIZING ABANDONMENT\* ABANDON\* SHOOT OR ACIDIZE CHANGE PLANS (Other) (Nors: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) Recomplete and commingle 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) Union Texas Petroleum desires to recomplete this well in the Gallup formation of the West Lindrith Gallup-Dakota pool and commingle with the Blanco Mesaverde. The comminglig will be pursuant to N.M.O.C.D. Order No: R-7507 dated April 20, 1984. The commingling will be completed as follows: 1. Set BP at 7100'+ isolating Dakota zone.

Run GR-CCL-CBL over Gallup interval. Squeeze if necessary.

- Perforate Gallup with 1 SPF at 6456',58',66',74',86',88', 6523',25',43', 50',68',78',85', 6605',07',14',17',27',31',33',38',46',52',55',65', 6927', 29',47',51'.
- Acidize with 2400 gals 15% HCl and 58 7/8" ball sealers.
- 5. Frac with 100,000# 20/40 sand in 76,000 gals 20# x-linked gelled water.
- Drill out BP.
- 7. Clean up well.
- Run 2-3/8", 4.7# tubing to 7300'+. 8.
- Resume production.



18. I hereby certify that the foregoing is true and correct Permit Coordinator 06/23/1987 DATE TITLE SIGNED (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY: AREA MANAGER FARMINGTON RESOUT DE AT See Instructions on Reverse Side