Distribution: C	0+4 (BLM); 1-Accounting; 1-3	Land; 1-File		
Form 3160-5 (June 1990)				FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reem the holider en ि ச் அல்லில் Use "APPLICATION FOR PERMIT" for such proposals				5. Lease Designation and Serial No. SF-079071-B
				6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE U/U HAMMINGTON, MAN				7. If Unit or CA, Agreement Designation
1. Type of Well Oil Well Other			1000 12 3 7 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CANYON LARGO UNIT
Name of Operato			MAY 2000	Canyon Largo Unit #315
Merrion (Oil & Gas Corporation	(14634)	OLOGNEDY -	9. API Well No.
	Avenue, Farmington, NM 87401	-2634	(505) 327-9801 >	30-039-23011 10. Field and Pool, or Exploratory Area
	(Footage, Sec., T., R., M., or Survey Description			Devils Fork Gallup
1770' fn	l & 1740' fwl (se nw)			11. County or Parish, State
Section 28, T25N, R6W				Rio Arriba County, New Mexico
12. (CHECK APPROPRIATE BOX (s) TO INDICA	TE NATURE OF NOTICE, REPO	
	(PE OF SUBMISSION	TYPE OF ACTION		
	Notice of Intent		Abandonment	Change of Plans
<u> </u>	None of Brent		Recompletion	Change of Plans
X Subsequent Report Final Abandonment Notice		<u> </u>	·	New Construction
			Plugging Back	Non-Routine Fracturing
			Casing Repair	Water Shut-Off
			Altering Casing	Conversion to Injection
		<u>X</u>	Other Temporary Abandonment	Dispose Water
				(Note: Report results of multiple completion on Completion or Recompletion Report and Log form.)
	d or completed Operations (Clearly state all perti ace locations and measured and true vertical dept			g any proposed work. If well is directionally drilled,
March 13, 2000	MIRU A-Plus Well Service 3/13	3/00. SDON.	Note: Notified BLM at 8:20 AM of	on 3/13/00.
March 14, 2000	Check pressures – Csg 300 psi, Tbg 300 psi. NU blow down line, blow down casing to 50 psi. Blow down tubing to 50 psi. Pump 30 bbls water down tubing to kill well. ND WH, NU BOPs and test. POH and tally 195 joints (6141'). POH with 194 joints, seating nipple, 1 joint with sawtooth collar lay 3 joints down. RU A-Plus Wireline, ran 4-1/2" gauge ring to 6000'. RU 4-1/2" CIBP and set at 5950'. RIH with 4 joints and LD. RIH with 188 joints to 5920' + 13' KB = 5933'.			
March 15, 2000	Open well 0 psi. Load hole with 85 bbls, circulate clean. Circulate 10-15 bbls to production tank. Pressure tested 4-1/2' casing to 300 psi – held OK for 15 mins. Circulate inhibitor fluid with 100 bbls, 1 gal/10 bbls water. Land tubing, ND BOPs, NU WH. Shut in well. RDMOL. Note: 7 joints on ground. 188 joints 2-3/8" in hole, 5933' with 13' KB.			
		24) Pop(DVALEYPROBE JAN O	1 2001
14. I hereby certify the	at the foregoing is true and code t	Tit	le Drlg & Prod Manager	Date 3/20/00
Steven S.				ACCI- TED FOR RECORD
	ederal or State office use)	pent.		Dec
Approved By Conditions of app	oroval, if any:	Titl		- Date 4AR 2 7 2000
		igly and willfully to	make to any department or agency of the United	States any false, fictitious or fraudulents grements
or representations as to	any matter within its jurisdiction.			Y M