Form 9-331	UNITED STATES	SUBALIT IN TRIPLICATI	Form approved. Budget Bureau No. 42-R1424.
(Ma: 1963)	PARTMENT OF THE INTI	ERIOR (Other in tructions of the	5. LEASE DESIGNATION AND SERIAL NO.
U	GEOLOGICAL SURVEY	, ll /	NM-19803
CLIV IDDY	NOTICES AND DEPORT	S ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	NOTICES AND REPORT for proposals to drill or to deepen or please the proposals of the propo		
1.			7. UNIT AGREEMENT NAME
OIL GAS WELL	OTHER		East Puerto Chiquito Mancos
2. NAME OF OPERATOR			S. FARM OR LEASE NAME
BENSON-MON	NTIN-GREER DRILLING (CORP.	
3. ADDRESS OF OPERATOR	9. WELL NO.		
221 Petrol	г√ 38 (н-8)		
4. LOCATION OF WELL (Report See also space 17 below.) At surface	location clearly and in accordance with	any State requirements.	Puerto Chiquito Mancos, East
1980' FNL	, 660 FEL, Sec. 8, T2		Sec. 8, T26N, RIE N. Rio Arriba New Mexico
14. PERMIT NO.	15. ELEVATIONS (Show whether	er DF, kT, GR, etc.) J	RV 12. COUNTY OR PARISH 13. STATE
:	7051	' GR GICAL N	Rio Arriba New Mexico
16. CI	neck Appropriate Box To Indicat	te Nature of Notice Report, or	Other Data
NOTICE	OF INTENTION TO:	SUBSI	QUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS		intermediate csg x
(Other)	_	(Note: Report resul Completion or Recor	ts of multiple completion on Well spletion Report and Log form.)
proposed work. If well nent to this work.)	LETED OPERATIONS (Clearly state all pertis directionally drilled, give subsurface	locations and measured and true vert	s, including estimated date of starting any cal depths for all markers and zones perti-

5/10/83 Ran 65 joints 2051.85' T0--2068.75 overall / 8-round Range 2 Lonestar casing. Landed at 2050'. Cemented with 160 cu ft of slurry 50/50 POZ mix, 4% gel, 6-1/4# Gilsonite/sack cement, 1/4# of celoflake/ sack of cement followed with 120 cu ft Class B regula cement slurry with additives.

> Texas pattern guideshoe Equipment used:

Regular float collar

6 centralizers located on joints

1-3-5-7-9-11

Cement top by Wilson Service Company temperature survey 500' below surface.

5/13/83 Pressure tested 7" casing to 1500# with zero pressure drop in 30 minutes.

5/18/83 To reached 3081' Plug back TO 3074'
Open hole Completion 306123074'

8. I hereby cerrify that the foregoine is true and correct		Vice-President	DATE June 7, 1983
(This space for Federal or State office use)	TITLE		
APPROVED BY	TITLE	141.5.0.0	

*See Instructions on Reverse Side

FARMINGTON DISTRICT SMM