Form 3160-5 (November 1983) (Formerly 9-331)	DEPART	UNITED STATI		SUBMIT IN TRIPLIC	Expires August 37, 7985 5. LEASE DESIGNATION AND SERIAL NO.
(10/111/19-551)		AU OF LAND MAN	-	,	
					Contract No 150 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use	SUNDRY NOT this for proper	TICES AND REP PAGE to drill or to deep CATION FOR PERMIT—	PORTS ON	WELLS Prop. Specifical Specification of the Control of the Contro	
1.	Use "APPLIC	CATION FOR PERMIT—	for such proper		- Pacai I I a Apache
OIL CA	ELL OTHER		6		7. UMIT AGREEMENT NAME
2. NAME OF OPERATE Union Texa	rom is Petroleum	Corporation			8. FARM OR LEASE NAME Jicarilla G
3. ADDRESS OF OPE			0=100	OIL GOIM, B	. V 6 9. WELL NO.
		gton, New Mexic		<u>, . Dist.</u> 37	1E ,
See also space I'	7 below.)	clearly and in accordance		requirements.*	10. FIELD AND POOL, OR WILDCAT
At surface	1	656' FNL;1979'	FWL		Basin Dakota
					11. SEC., T., R., M., OR RUK. AND SURVEY OR AREA
					Soc 1 TOON DELL NMDM
14. PERMIT NO.		15. ELEVATIONS (Show	15. ELEVATIONS (Show whether Dr. RT, GR, etc.)		Sec. 1, T26N-R5W NMPM
		7285' GR		Rio Arriba New Mexico	
16.	Check A	ppropriate Box To I	ndicate Natur	e of Notice, Report,	or Other Data
	NOTICE OF INTER	TO:	1		BARQUENT REPORT OF :
TEST WATER SE	IUT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	.	MULTIPLE COMPLETE		PRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDI	28	ABANDON®		BHOOTING OR ACIDIZING	
REPAIR WELL		CHANGE PLANS		(Other) Spud, d	rilled, and cased X
(Other)				(NOTE : Report r	esults of multiple completion on Well
nent to this wo	14-3/4" hole	at 12:45 PM 8,	/20/84.	ily and give pertinent	ecompletion Report and Log form.) dates, including estimated date of starting any vertical depths for all markers and sones perti-
1. Spud 2. Drill 3. Set 1 4. Cement surface 5. Pression Drill 7. Ran It 8. Ran 5 and 6 Cement Cement Tail to Ce	14-3/4" hole ed 14-3/4" hole ed 14-3/4", 40.5# ted 10-3/4" ce. WOC. ure tested ced 9-7/8" honduction, FDI -1/2", 15.5# 524'. ted 1st stage ted 2nd stage w/100 sx (11:	at 12:45 PM 8, ole to 545' RKE, K-55, ST&C @ with 495 sx (58 asing to 1500 Fle to 6589' and C/CNL logs. & 17#, K-55, Se with 380 sx (e with 620 sx 8 cu.ft.) Cl "Ee with 650 sx (Cl "B".	/20/84. B. 539'. 84 cu.ft.) PSI. Held d 7-7/8" ho ST & C casi (479 cu.ft.) (1054 cu.ft)	Cl B cement. ok. ole to 8450' 9/ ing to 8430' wi 50/50 POZ, 20 to 50/50 POZ, 20 12.	dates, including estimated date of starting any vertical depths for all markers and somes perti-
1. Spud 2. Drill 3. Set 1 4. Cement surface 5. Press 6. Drill 7. Ran II 8. Ran 5 and 6 Cement Cement Cement Tail to Cement Tai	14-3/4" hole ed 14-3/4" hole ed 14-3/4" hole of 10-3/4" ted 10-3/4" ted 10-3/4" hole ed 9-7/8" hole nduction, FDO 1/2", 15.5# 524'. ted 1st stage ted 2nd stage w/100 sx (11% ted 3rd stage w/18 cu.ft. down at 9:45 that the forefoling is that the forefoling is the	at 12:45 PM 8, ole to 545' RKE, K-55, ST&C @ with 495 sx (58 asing to 1500 Fle to 6589' and C/CNL logs. & 17#, K-55, Se with 620 sx 8 cu.ft.) Cl "Ee with 650 sx (Cl "B". PM 9-12-84.	/20/84. B. 539'. 84 cu.ft.) PSI. Held d 7-7/8" ho ST & C casi (479 cu.ft. (1054 cu.ft) 3" w/2% CaC (1865 cu.ft)	Cl B cement. ok. ole to 8450' 9/ ing to 8430' wi 50/50 POZ, 20 to 50/50 POZ, 20 12.	Cement circulated to 11/84. th stage tools at 4226' % gel, .6% FLA, 10# salt/sx. w/4% gel, 12-1/2# gilsonite/sx /12% gel, 12-1/2# gilsonite/sx /12% gel, 12-1/2# gilsonite/sx
1. Spud 2. Drill 3. Set 1 4. Cemen surface 5. Press 6. Drill 7. Ran II 8. Ran 5 and 6 Cemen Cemen Tail to Cemen Ta	14-3/4" hole ed 14-3/4" hole ed 14-3/4" hole ed 10-3/4" ce. WOC. ure tested ced 9-7/8" honduction, FDI 15.5# 524'. ted 1st stage ted 2nd stage w/100 sx (11sted 3rd stage w/118 cu.ft. down at 9:45	at 12:45 PM 8, ole to 545' RKE, K-55, ST&C @ with 495 sx (58 asing to 1500 Fle to 6589' and C/CNL logs. & 17#, K-55, Se with 620 sx 8 cu.ft.) Cl "Ee with 650 sx (Cl "B". PM 9-12-84.	/20/84. B. 539'. 84 cu.ft.) PSI. Held d 7-7/8" ho ST & C casi (479 cu.ft.) (1054 cu.ft) 3" w/2% CaC (1865 cu.ft)	Cl B cement. ok. ole to 8450' 9/ ong to 8430' with the second of the se	Cement circulated to 11/84. th stage tools at 4226' % gel, .6% FLA, 10# salt/sx. w/4% gel, 12-1/2# gilsonite/sx /12% gel, 12-1/2# gilsonite/sx /12% gel, 12-1/2# gilsonite/sx /12% gel, 12-1/2# gilsonite/sx
1. Spud 2. Drill 3. Set 1 4. Cemen surface 5. Press 6. Drill 7. Ran II 8. Ran 5 and 6 Cemen Cemen Tail to Cemen Ta	14-3/4" hole ed 14-3/4" hole ed 14-3/4" hole ed 10-3/4" ce. WOC. ure tested ced 9-7/8" honduction, FDI 15.5# 524'. ted 1st stage ted 2nd stage w/100 sx (11sted 3rd stage w/118 cu.ft. down at 9:45	at 12:45 PM 8, ole to 545' RKE, K-55, ST&C @ with 495 sx (58 asing to 1500 Fle to 6589' and C/CNL logs. & 17#, K-55, Se with 620 sx 8 cu.ft.) Cl "Ee with 650 sx (Cl "B". PM 9-12-84.	/20/84. B. 539'. 84 cu.ft.) PSI. Held d 7-7/8" ho ST & C casi (479 cu.ft.) (1054 cu.ft) 3" w/2% CaC (1865 cu.ft)	Cl B cement. ok. ole to 8450' 9/ ong to 8430' with the second of the se	Cement circulated to 11/84. th stage tools at 4226' % gel, .6% FLA, 10# salt/sx. w/4% gel, 12-1/2# gilsonite/sx /12% gel, 12-1/2# gilsonite/sx /12% gel, 12-1/2# gilsonite/sx