

DENNIS

JICARILLA D #16.

PROCEDURE FOR ABANDONING
THE DAKOTA (8162' - 8396')

08.28.87

1. RECOVER B. PLUG AT 8340 FT.
2. R.I.H. OPEN ENDED TO 8400 FT.
CIRC. BTMS. UP.
3. MIX AND DISPLACE 15.8[#]/GAL NEAT
CEMENT (RETARDED FOR 2 1/2 HRS. PUMP TIME).
"UNDER DISPLACE BY TWO BBLs TO
ALLOW FOR PULLING DRY PIPE".
4. P.O.H. TO 7840 FT. AND REVERSE
CIRC. (MINIMUM OF 225 BBLs.)
5. P.O.H TO 6500 FT. AND
W.O.C. OVER NIGHT.
6. FEEL PLUG, AND IF
PLUG IS ABOVE 8000 FT.
PROCEED WITH GAMUP
COMPLETION.

CEMENT TOP
+ OR - 7850 FT.

PERFORATIONS.
8162 - 8396 FT.

Wayne.

PSTD. 8460

T.D. 8500 FT.