



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA  
1235 LAPLATA HIGHWAY  
FARMINGTON, NEW MEXICO 87401

TAKE  
PRIDE IN  
AMERICA

IN REPLY REFER TO:

SF-079366 et. al. (WC)  
3162.3-1(F) (019)

JUN. 1 3 1991

**RECEIVED**  
JUN 4 1991  
OIL CON. DIV.  
DIST. 3

Union Oil of California  
Attention: Mr. Bill Hering  
3300 N. Butler, Suite 200  
Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill (APD) well Nos.:

- ✓ 1. No. 244 Rincon Unit, SW/4NE/4 sec. 21, T. 27 N., R. 6 W., SF-079366.
- ✓ 2. No. 245 Rincon Unit, SW/4NE/4 sec. 22, T. 27 N., R. 6 W., SF-079365-A.
- ✓ 3. No. 247 Rincon Unit, SE/4NE/4 sec. 26, T. 27 N., R. 6 W., SF-079367-A.
- ✓ 4. No. 248 Rincon Unit, NW/4SW/4 sec. 26, T. 27 N., R. 6 W., SF-079367-A.
- ✓ 5. No. 249 Rincon Unit, SE/4NE/4 sec. 27, T. 27 N., R. 6 W., SF-079366.
- ✓ 6. No. 250 Rincon Unit, SE/4NE/4 sec. 28, T. 27 N., R. 6 W., SF-079364.
- ✓ 7. No. 267 Rincon Unit, SE/4NE/4 sec. 31, T. 27 N., R. 6 W., SF-079364.
- ✓ 8. No. 268 Rincon Unit, NE/4SW/4 sec. 31, T. 27 N., R. 6 W., SF-079364.
- ✓ 9. No. 275 Rincon Unit, SE/4SW/4 sec. 24, T. 27 N., R. 7 W., SF-079298-D.
- ✓ 10. No. 282 Rincon Unit, NE/4NE/4 sec. 22, T. 27 N., R. 7 W., SF-079360.
- ✓ 11. No. 283 Rincon Unit, NE/4SW/4 sec. 23, T. 27 N., R. 7 W., SF-080385.
- ✓ 12. No. 284 Rincon Unit, NE/4NE/4 sec. 26, T. 27 N., R. 7 W., SF-080385.
- ✓ 13. No. 285 Rincon Unit, NW/4NE/4 sec. 27, T. 27 N., R. 7 W., SF-080385.
- ✓ 14. No. 288 Rincon Unit, SW/4SW/4 sec. 28, T. 27 N., R. 7 W., SF-080213.
- ✓ 15. No. 289 Rincon Unit, SE/4NE/4 sec. 33, T. 27 N., R. 7 W., SF-080213.
- ✓ 16. No. 296 Rincon Unit, SW/4SW/4 sec. 11, T. 26 N., R. 7 W., SF-079160.
- ✓ 17. No. 9 Day "B", NE/4SW/4 sec. 7, T. 27 N., R. 8 W., SF-078571.

All wells located in Rio Arriba County, New Mexico. The subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

## ABANDONED LOCATION

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller  
Chief, Branch of Mineral Resources

Enclosures

cc:  
New Mexico Oil Conservation Division