

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

070 FARMINGTON, NM

1. Type of Well  
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
UNION OIL COMPANY OF CALIFORNIA

3. Address and Telephone No.  
P.O. Box 2620, Casper, WY 82602 (307) 234-1563 Ext. 116

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
790' FNL & 790' FWL  
Sec. 6, T26N-R6W

5. Lease Designation and Serial No.

SF 07930

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

RINCON UNIT

8. Well Name and No.

150E

9. API Well No.

30-039-25359

10. Field and Pool, or Exploratory Area

Basin Dakota/Blanco

11. County or Parish, State M.V.

Rio Arriba

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☒ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion or Completion or Recompletion Report and Log)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Rincon Unit Well No. 150E was originally permitted and drilled as a Basin Dakota/South Blanco Tocito well. The well was spudded 5-5-95 and TD'd @ 7620' 5-21-95. The well was logged and 7" production casing was run and cemented. The Dakota/Graneros was perforated, fracture stimulated and tested. A bridge plug was set above this interval and the Tocito was perforated, fracture stimulated and tested. The Tocito proved to be non-productive during testing and was squeezed. The well was cleaned out and returned to a Dakota producer 7/95.

Unocal proposes to perforate, fracture stimulate and test the well in the Mesaverde interval and if productive, complete the well as a dual Dakota/Mesaverde producer.

Attached is a new well location and acreage dedication plat for Well #150E.

14. I hereby certify that the foregoing is true and correct

Signed

*Tom Benson*

Title Drilling Superintendent

Date 9-12-95

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

APPROVED

Date

SEP 15 1995

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side

NMOCD

DISTRICT MANAGER

District I  
PO Box 1988, Hobbs, NM 88241-1988  
District II  
PO Drawer DD, Artesia, NM 88211-0719  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
PO Box 2088, Santa Fe, NM 87504-2088

State of New Mexico  
Energy, Minerals & Natural Resources Department

OIL CONSERVATION DIVISION  
PO Box 2088  
Santa Fe, NM 87504-2088

Form C-102  
Revised February 21, 1994  
Instructions on back  
Submitted to Appropriate District Office  
State Lease - 4 Copies  
Fee Lease - 3 Copies

95 SEP 14 PM 1:50 AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT, NM

API Number 30-039-25359	Pool Code 71599/73219	Pool Name Basin Dakota/Blanco Mesaverde
Property Code 011510	Property Name RINCON UNIT	Well Number 150-M
OGRID No. 023708	Operator Name UNOCAL	Elevation 6700

10 Surface Location

UL or lot no.	Section	Township	Range	Lot Ida	Feet from the	North/South line	Feet from the	East/West line	County
D	6	26N	6W		790	NORTH	790	WEST	RIO ARRIBA

11 Bottom Hole Location If Different From Surface

UL or lot no.	Section	Township	Range	Lot Ida	Feet from the	North/South line	Feet from the	East/West line	County

Dedicated Acre 322.29 320	Joint or Infill Y	Consolidation Code U	Order No. Unitization
---------------------------------	----------------------	-------------------------	--------------------------

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED  
OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

	<p>17 OPERATOR CERTIFICATION</p> <p>I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief</p> <p>Signature: <u>Jim Benson</u></p> <p>Printed Name: <u>Jim Benson</u></p> <p>Title: <u>Drilling Superintendent</u></p> <p>Date: <u>September 12, 1995</u></p>
	<p>18 SURVEYOR CERTIFICATION</p> <p>I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.</p> <p>Date of Survey: <u>September 20, 1993</u></p> <p>Signature and Seal of Professional Land Surveyor: <u>Cecil B. Tullis</u></p> <p>Cecil B. Tullis</p> <p>Certificate Number: <u>9672</u></p>