

Submit 3 Copies To Appropriate District Office

District I  
1625 N. French Dr. Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals & Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO. <b>30-039-26996</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name  <b>RINCON UNIT</b>
8. Well No. <b>164R</b>
9. Pool name or Wildcat <b>Blanco Mesa Verde</b>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>6551' GR</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator  
**PURE RESOURCES L.P.**

3. Address of Operator  
**P.O. BOX 850, BLOOMFIELD, NM 87413**

4. Well Location  
Unit Letter **K** : **1939'** feet from the **South** line and **2310'** feet from the **West** line  
Section **2** Township **26N** Range **07W** NMPM **RIO ARRIBA** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
**6551' GR**

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

**SUBSEQUENT REPORT OF:**


PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	OTHER: <input checked="" type="checkbox"/> Set Tubing		

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion)

**11/06/02 - MIRU DRAKE #19 - DRILL BRIDGE PLUG. 11/11/02 LANDED TUBING @ 7271'**

**SEE ATTACHED**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE San Juan Basin Drilling/ Production Foreman DATE 11/15/02

Type or print name Mike Phillips TELEPHONE NO. (505) 632-1811

This space for State Use ORIGINAL SIGNED BY CHARLIE T. PERRY DEPUTY OIL & GAS INSPECTOR, DIST. 03 NOV 18 2002

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Conditions of approval, if any:

Pure Resources, Inc.

Well History

RINCON UNIT #164R - 76.82% WI From 1/1/1920 through 11/15/2002

Well Name RINCON UNIT #164R - 76.82% WI  
State: NM County: RIO ARRIBA

Lease Well 521522-0164

11/6/2002 MIRU DRAKE #19 RIG; ND WH; NU BOP AND 7" BLOOIE LINE; PULL DONUT; FOUND HEAVY PARAFFIN IN TBG; TREAT WELL WITH 110 GALS PAS - 17; LEFT WELL SHUT IN OVERNIGHT.

11/7/2002 BLOW WELL DOWN TO BLOW PIT; TOH WITH 2 3/8" TBG; PUT WELL ON PRODUCTION; RU AIR PACKAGE; SDFN.

11/9/2002 TIH WITH 3 7/8" MILL AND 2 3/8" TBG; DRILL OUT BP AT 6900'; CLEAN OUT TO 7310'; CIRC HOLE CLEAN; TOH WITH 2 3/8" TBG AND MILL; PUT WELL ON PRODUCTION.

11/10/2002 RU COBRA WIRELINE; RUN AFTER FRAC LOG; TAG UP AT 7320'; NO SAND FILL; RD WIRELINE; PUT WELL ON PRODUCTION MAKING 1.2 MCF PER DAY; SDFN.

11/11/2002 TIH; LAND TBG@ 7271'; ND BOP; NU WH; TIH WITH SINKER BARS; KNOCK TBG PLUG LOOSE; PUT WELL ON PRODUCTION (14 HRS); RD TO MOVE.