


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No.

Unit



SUNDRY NOTICES AND REPORTS ON WELLS

MAR 13 1959

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	<input type="checkbox"/>
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	<input type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL	Casing record	<input checked="" type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 11, 1959

Federal

Well No. 1 is located 530 ft. from N line and 2110 ft. from E line of sec. 35

SE/4 Sect. 35
(1/4 Sec. and Sec. No.)

25N
(Twp.)

10W
(Range)

N.T.P.M.
(Meridian)

Monte Lora Hallap
(Field)

San Juan County
(County or Subdivision)

New Mexico
(State or Territory)


The elevation of the derrick floor above sea level is 6761 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 172 ft. 3 1/8" surface casing cemented w/80 sacks.

Set 5110 ft. 5 1/2" production casing cemented w/200 sacks.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Wellshire Development Company

Address 425 Petroleum Club Building

Denver 2, Colorado

By

Title

Secy.-Treas.