					1
Form 9-331 (May 1963)			SUBMIT IN TRIPLICATE.		ed. u No. 42-R1424.
(1113 1303)	DEPARTMENT OF THE INTERIOR (Other Instructions on re-			5. LEASE DESIGNATION	
	G	GEOLOGICAL SURVEY			15
	SUNDRY NOTE	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)				14-20-603-1304	
1.		7. UNIT AGREEMENT NAME			
	GAS WELL OTHER	East Bisti Unit			
NAME OF OPERATOR				S. FARM OR LEASE NAM	1E
Skelly	Oil Company				
3. ADDRESS OF OPERATOR				9. WELL NO.	-
1860 Li	.ncoln Street -	34			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			10. FIELD AND FOOL, OR WILDCAT Bisti Lower Gallup		
			11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
660' FN	IL & 1980' FWL	Section 30-25N-10W			
14. PERMIT NO.	14. PERMIT NO. 15. ELEVATIONS (Show to		F, RT, GR, etc.)	12. COUNTY OF PARISH	13. STATE
		6811' GR		San Juan	New Mexic
16.	Check Ap	propriate Box To Indicate N	Nature of Notice, Report, or C	Other Data	
	NOTICE OF INTENTION TO: SUBSEQU			UENT REPORT OF:	
TEST WATER	SHUT-OFF P	ULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
PUACTEUR TO	EAT V	ULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING C.	ASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

All depths shown are from ground level.

ARANDON* CHANGE PLANS

Spotted cement plug 5172-5072'. 7/21/71 MI & RU Aztec Well Service Unit. Pulled rods. Pulled tubing. Worked 5-1/2" casing to free same. Rigged up blue jet and shot 5-1/2" casing off at 1542'. Spotted cement plug 1592-1390', 50' inside casing and 152' above casing stub. Pulled up the hole and spotted cement plug 760-660'. 37 jts. (1550') 5-1/2" casing.

SHOOTING OR ACIDIZING

Installed dry hole marker. Spotted 10' cement plug in surface casing.

Completed P&A 7/24/71.

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

18.

I hereby certify that the foregoing is true and correct SIGNED	t Lead Clerk	DATE 10-26-71
(This space for Federal or State office use)		
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE