


(SUBMIT IN TRIPLICATE)

Indian Agency _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	NEW N
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Casing perforating record	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

No. 9-01

March 1

, 19 59

Well No. 2 is located 560 ft. from [N] line and 2080 ft. from [E] line of sec. 19

SE/4 Sect. 19

(1/4 Sec. and Sec. No.)

25 N 10W

(Twp.)

(Range)

N.M.P.M.

(Meridian)

Bisti Lower Gallup

(Field)

San Juan County

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 6586 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Perforated production casing with Jet Perforations, 1/4 ft.

5156' - 5157' - 2 holes
5156' - 5166' - 80 holes
5088' - 5110' - 88 holes

170



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Wellshire Development Company

Address 425 Petroleum Club Building

Denver 2, Colorado

By

Secy.-Treas.

Title