werr Z

At surface

UNITED STATES DEPARTMENT OF THE INTERIOR (Other Instructions on re-

SUBMIT IN TRIPLICATE.

Porm approved, Budget Bureau No. 42-R1424, 5. LEASE DESIGNATION AND BERIAL NO.

GEOLOGICAL SURVEY

14-20-603-1311 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT..." for such proposals,) Navajo Tribal East Bisti Unit 2. NAME OF OPERATOR 8. FARM OR LEASE NAME Skelly Oil Company 3. ADDRESS OF OPERATOR 9. WELL NO. 1860 Lincoln Street, Denver, Colorado 80203 20 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) 10. FIELD AND POOL, OR WILDCAT

1980' FSL & 720' FWL Section 23-25N-11W

Section 23-25N-11W

Bisti Lower Gallup

14. PERMIT NO. 16. ELEVATIONS (Show whether DF, RT, GR, etc.)

12. COUNTY OR PARISH; 13. STATE

San Juan New Mexico

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

6481' KB

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE		PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON*	x	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING	REFAIRING WELL ALTERING CASING ABANDONMENT®
REPAIR WELL (Other)		CHANGE PLANS		(Other) (Nors: Report results of mul Completion or Recompletion R	tiple completion on Well eport and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

This well has reached the economic limit and is no longer profitable to operate. Plans are to plug and abandon this well; plugging as follows:

First Plug - 100' plug across Gallup Zone perforations 4946-4988'

Second Plug - 50' inside the 5-1/2" casing and 50' above where casing is shot in two Third Plug - 150' cement plug extending downward from above the Fruitland Coal section across the Pictured Cliffs Sand

Fourth Plug - 100' plug at bottom of Ojo Alamo Sand (unless surface casing is set through the Ojo Alamo Sand)

10 sacks of cement in top of surface casing with dry hole marker



			DIST. 3	
18. I hereby certify that the toregon is true and correct SIGNED	TITLE District		DATE June 10, 1971	_ L_
(This space for Federal or State office use)				=
APPROVED BY	TITLE	· · · · · · · · · · · · · · · · · · ·	DATE	-