

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.  
E. W. Mudge No. 1  
SF 078061  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Fresh Water Source	7. UNIT AGREEMENT NAME Carson Unit
2. NAME OF OPERATOR Shell Oil Company	8. FARM OR LEASE NAME Unit <i>Water well</i>
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80290	9. WELL NO. 4-20
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 44.6' FNL & 2105.2' FWL Section 20	10. FIELD AND POOL, OR WILDCAT Bisti
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6418 KB
12. COUNTY OR PARISH San Juan	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

See attachment

WILL SEND FINAL SUNDRY WHEN LOCATION  
CLEANED AND READY FOR INSPECTION

18. I hereby certify that the foregoing is true and correct

SIGNED *P. Plaster* TITLE Div. Ops. Engr. DATE SEP 27 1977

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

cc: NMO&GCC

\*See Instructions on Reverse Side

PLUG & ABANDON

SHELL OIL COMPANY

FROM: 8/22-26/77

LEASE CARSON UNIT

DIVISION WESTERN

COUNTY SAN JUAN

WELL NO.

ELEV

STATE

BISTI

4-20 WS

6418 KB

NEW MEXICO

NEW MEXICO

CARSON UNIT

Unit 4-20 WS

(P&A)

"FR" TD 3850. PB 3847. 8/17: AFE 570066 provides funds to P&A. RU Bedford. Pulled 39 1" rods and 80 7/8" rods. 8/18: Pulled 102 jts 2-7/8" tbg & anchor. Ran 2-3/8" tbg open ended to 3847'. Circ. 8/19: Spotted 220 sx plug in two stages across and above perfs 2806-3326, 3525-3812. Pulled tbg above plug. 8/20: Pulled tbg & shot 4 holes @ 1160. Spotted 100 sx, displaced 40 sx thru perfs. Pulled tbg. Perf 4 holes @ 400'. Spotted 60 sx. Pulled tbg. Displaced 20 sx into perfs. AUG 22 1977

Unit 4-20 WS  
(P&A)

TD 3850. PB 3847. No report. AUG 23 1977

Unit 4-20 WS  
(P&A)

TD 3850. PB 3847. No report AUG 24 1977

Unit 4-20 WS  
(P&A)

TD 3850. PB 3847. No report. AUG 25 1977

Unit 4-20 WS  
(P&A)

AUG 26 1977

TD 3850. PB 3847. Placed 10 sx cmt plug @ surface. Installed abandonment marker.  
FINAL REPORT