



FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

SF 088724A 078062A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA. Agreement Designation

1 Carson Unit

8. Well Name and No.

44-18

9. API Well No.

30-045-05338

10. Field and Pool, or Exploratory Area

Bisti Lower Gallup

11. County or Parish, State

San Juan, New Mexico

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
Central Resources, Inc.

3. Address and Telephone No.
P.O. Box 1213, Bloomfield, New Mexico 87413 (505)-632-3476

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
660' FSL, 659' FEL, Sec 18, T25N, R11W

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Central Resources, Inc. intends to plug the well in accordance with regulations. Production equipment will be removed and well will be plugged as specified. Perforate and squeeze will be used.

Proposed Procedure:

A. Notify the Farmington BLM Office at 505-599-8907 24 hours prior to commencement of plugging operations.

B. Pull all retrievable downhole production equipment.

C. Set a CIBP at 4887' to 4906'. *gallup top @ 4729'*

D. Set a 100' cement plug from 3981 to 3781 Across Mancos top at 3881' inside and outside 4 1/2" casing.

E. Set a 100' cement plug from 2157' to 1957' Across *Menefee top at 2057'* inside and outside the 4 1/2" casing.

F. Set a 100' cement plug from 1331 to 1131' Across Pictured Cliffs top at 1231' inside and outside the 4 1/2" casing.

G. Set a 100' cement plug from 971' to 771' Across Fruitland Coal top at 871' inside and outside the 4 1/2" casing.

H. Set a cement plug from surface to 168' across the surface casing shoe at 118' inside and outside the 4 1/2" casing.

I. Cut wellhead and install dry hole marker. Clear and remediate location.

14. I hereby certify that the foregoing is true and correct

Signed *Stacy Schubert*

Title Production Tech.

Date

April 9, 2001

(This space for Federal or State office use)

Approved by

Title

Date

5/22/01

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any manner within its jurisdiction.

*See Instruction on Reverse Side

NMOCD