

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir,
Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. SF 078067
2. Name of Operator Giant Exploration & Production Company	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. P.O. Box 2810, Farmington, New Mexico 87499 (505)326-3325	7. If Unit or CA. Agreement Designation Carson Unit
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FNL, 660' FEL, Sec. 14, T25N, R12W	8. Well Name and No. Carson Unit #42-14
	9. API Well No. 30-045-05400
	10. Field and Pool, or Exploratory Area Bisti Lower Gallup
	11. County or Parish, State San Juan, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input checked="" type="checkbox"/> Other <u>Return to Production</u>
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Giant Exploration & Production Company intends to return the subject well to production as follows:

- 1) Clean out to a PBD of 5033'.
- 2) Pressure test casing.
- 3) Acidize existing perforations (4860'-86', 4890'-4900', 4939'-49', 4954'-64') with 1000 gal. 15% HCl.
- 4) Install production tubing string. (Note: if casing leaks are encountered, a 3-1/2" liner with isolating packers will be run across the leaking interval prior to running the production string.)
- 5) Install pumping unit.
- 6) Return well to production.

14. I hereby certify that the foregoing is true and correct		
Signed <u>Paul R. Williams</u>	Title <u>Area Engineer</u>	Date <u>SEP 07 1995</u>
(This space for Federal or State office use)		
Approved by _____	Title _____	Date _____
Conditions of approval, if any:		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any manner within its jurisdiction.

*See Instruction on Reverse Side

APPROVED

SEP 12 1995

DISTRICT MANAGER

NMOCD