SUBMIT IN TRIPLICATE*
(Other instructions on re-UNITED STATES

Form approved, Budget Bureau No. 42-R1424.

			A				
5.	LEASE	DES	IGNATION	AND	SER	IAL	NO.
	Ε.	W.	Mudge	No	٠.	2	
	SĚ	ÖŽ	Mudge 3062		•	_	

DEPA	E. W. Mudge No. 2 SF 078062				
SUNDRY N	6. IF INDIAN, ALLOTTEE	OR TEIBE NAME			
OIL GAS WELL OTH NAME OF OPERATOR Shell Oil Company	7. UNIT AGREEMENT NA Carson Unit 8. FARM OR LEASE NAM				
ADDRESS OF OPERATOR			9. WELL NO. 31-17		
1700 Broadway, Denve	er, Colorado 80290				
LOCATION OF WELL (Report loca See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT Bisti				
658' FNL & 1975' FEI	Section 17		11. sec., T., R., M., OR B SURVEY OR AREA Section 17-	T25N-R11W	
14. PERMIT NO.	, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE		
	6362.5' KB		San Juan	N. Mexico	
6. Check	ther Data				
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING V	CELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	ASING	
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMEN	X X	
REPAIR WELL	CHANGE PLANS	(Other)			
(Other)	(Note: Report resu				
I O O O O O O O O O O O O O O O O O O O	ED OPERATIONS (Clearly state all pertines lirectionally drilled, give subsurface loca	at details and give pertinent dates.	including estimated date	e of starting a	

See attachment

WILL SEND FINAL SUNDRY WHEN LOCATION CLEANED AND READY FOR INSPECTION

MAR 1 9 1984

AUG 1 1977

U. S. GEOLOGICAL SURVEY

OIL CON. DIV. DIST. 3

. I hereby certify that the toregoing is true and correct		7 0 0 1077
SIGNED Landy	TITLE	Div. Opers. Engr. DATE 301 2 9-1977
(This space for Federal or State office use)		
APPROVED BY	TITLE	Ditte 1924
		en de la companya de A companya de la comp

*See Instructions on Reverse Side

NMOCD

AREA MANAGER

PLUG AND ABANDON WELL	•			BISTI
SHELL OIL COMPANY	LEASE	CARSON UNIT	WELL NO.	31-17
SHELL OIL COMMAN	DIVISION	WESTERN	ELEV	63 62. 5 KB
FROM: . 7/11-13/77	COUNTY	SAN JUAN	STATE	NEW MEXICO

NEW MEXICO
BISTI FIELD
Carson Unit 31-17
(P&A)

"FR" TD 5040. PB 4936. WO #527936 provides funds to plug & abandon well. 7/9 RU Bedford. Unseated Bkr R pkr. Pulled & LD pkr & 152 jts tbg. Started back in hole w/tbg workstring.

JUL 1 1 1977

Carson Unit 31-17 (P&A)

TD 5040. PB 4936. Ran tbg workstring to PBTD. Loaded hole w/mud. Spt'd 20 sx cmt plug over & above perfs. Pulled & LD tbg. RU hyd jacks. JUL 12 1977

Carson Unit 31-17 (P&A)

TD 5040. PB 4936. Shot off csg @ 2029' & spt'd 35 sx cmt plug @ csg stub. Pulled csg to 1320' & spt'd 50 sx cmt plug. Pulled csg to 470' & spt'd 25 sx cmt plug @ 0jo Alamo. Fin'd pull'g csg. Installed abandonment marker & RD Bedford 7/13/77.

FINAL REPORT

