

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
Mims No. 1
SF 078067
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME Carson Unit
2. NAME OF OPERATOR Shell Oil Company	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80290	9. WELL NO. 44-11
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 660' FEL Section 11	10. FIELD AND POOL, OR WILDCAT Bisti
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6378.8 KB
12. COUNTY OR PARISH San Juan	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See attachment

WILL SEND FINAL SUNDRY WHEN LOCATION
CLEANED AND READY FOR INSPECTION

18. I hereby certify that the foregoing is true and correct

SIGNED <i>E. Plaudy</i>	TITLE Div. Opers. Engr.	DATE MAY 25 1977
-------------------------	-------------------------	------------------

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:
cc: New Mexico O&GCC

PLUG AND ABANDON

SHELL OIL COMPANY

FROM: 5/20-24/77

LEASE CARSON UNIT

DIVISION WESTERN

COUNTY SAN JUAN

BISTI FIELD

WELL NO. 44-11

ELEV 6378.8 KB

STATE NEW MEXICO

NEW MEXICO

BISTI FIELD

Carson Unit 44-11
(P&A)

"FR" TD 5035. PB 5020. AFE #527926 provides funds to plug & abandon well. RU Bedford Inc. Found tbg stuck. Stretch indicates it's stuck close to btm; unable to pull tbg. Filled backside w/wtr; held about 20 bbls. Filled tbg w/3 BW. Press'd to 1000#. Could not pmp into frm @ 1000# nor get any communication betwn tbg & annulus. Press'd csg to 800#; could not pmp any fluid away. Ran WL in tbg; could not get below 875'. Backed off on tbg string @ 1908. Pulled & LD tbg. Ran tbg workstring to tbg stub @ 1908. Filled hole w/mud. Spt'd 20 sx cmt. Pulled & LD tbg.

MAY 20 1977

Carson Unit 44-11
(P&A)

TD 5035. PB 5020. RU hyd jacks; found only 1150' free pipe. Shot 4 holes/ft @ 1500'. Sqz'd 35 sx cmt thru perfs @ 350# avg press. Had 550# max press when displ-mt took place. Press bled off in less than 5 mins. SI well. 5/21 Shot off csg @ 1286'. Spt'd 50 sx cmt @ csg stub. Pulled csg to base of Ojo Alamo. Spt'd 35 sx cmt. Pulled csg to base of 8-5/8 csg. Spt'd 25 sx cmt. Fin'd pull'g csg. RD Bedford Inc. 5/21/77.

MAY 23 1977

Carson Unit 44-11
(P&A)

TD 5035. PB 5020. Spt'd 10 sx cmt plug. Installed abandonment marker 5/23/77.

FINAL REPORT

MAY 24 1977