

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

SF-078063

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Carson Unit

8. Well Name and No.
Carson Unit #41-19

9. API Well No.

30-045-13271

10. Field and Pool, or Exploratory Area

Basin Fruitland Coal

11. County or Parish, State

San Juan, New Mexico

SUBMIT IN TRIPLICATE

1. Type of Well

Oil Well Gas Well Other

2. Name of Operator

Giant Exploration & Production Company

3. Address and Telephone No.

P.O. Box 2810, Farmington, NM 87499 (505) 326-3325

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

657' FNL, 614' FEL, Sec. 19, T25N, R11W

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See Attachment "A"

RECEIVED

SEP 10 1993

OIL CON. DIV. 1
DIST. 3

OPO REGISTRATION, NMI

08 SEP -2 AM 11:00

RECEIVED
BLM

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct

Signed John C. Corbett Title Senior Vice President Date 8/31/93

(This space for Federal or State office use)

Approved by _____ Title _____ Date SEP 07 1993

APPROVED

DISTRICT MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

Giant Exploration & Production Company
Carson Unit #41-19
Attachment "A"

Giant Exploration & Production Co. plans to plug and abandon the above location as follows:

1. Move on location. Circulate wellbore through 2-3/8" tubing string.
2. Spot a 50 sack (59 cuft) cement plug over the Fruitland Coal perforations from 1179'-1195'. Plug #1 will consist of 50 sacks (59 cuft) of Class "B" cement spotted inside the 4-1/2", 9.5# casing. Squeeze 10 sacks (11.8 cuft) into the perforations. Cement plug will cover the top of the Fruitland Coal formation from 1195' to 845'.
3. Perforate 4 squeeze holes at 345' to allow coverage of the Ojo Alamo formation from 345' to surface. Circulate 165 sacks (194.7 cuft) of cement from 345' to surface leaving both the inside and outside of the casing full of cement.
4. Cut off the wellhead and install a regulation dry hole marker.

IN REPLY REFER TO:
(07337)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT
FARMINGTON DISTRICT OFFICE
1235 La Plata Highway
Farmington, New Mexico 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: A/-19 Carson Unit

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
2. **Mike Flaniken** with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
3. The following modifications to your plugging program are to be made (when applicable):

1.) Spot a cement plug from 1700' (Top of CIBP)
to 904' Tag TOC. (Isolate PC & Fruitland
from Mesavude and puts. ~ 3573'-3631')

Office Hours: 7:45 a.m. to 4:30 p.m.