

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

N00-C-14-20-2727

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo Tribe

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Navajo Tribe "BR"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Tocito Dome Penn D

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

3, T25N, R18W

12. COUNTY OR PARISH 13. STATE

San Juan

New Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
TEXACO, Inc. Prod. Dept. West U.S.

3. ADDRESS OF OPERATOR
P. O. Box EE, Cortez, CO. 81321

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
NE 1/4 NW 1/4 Sec. 3

510' from North line and 1980' from West line.

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
5712' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-15-77. MIRUSU. Filled hole with mud. Spot & squeezed 35 sx.

cement plug from 6306 - 6498'. Run free point survey, cut

csg. off at 2565'. Set 75 sx. cement plug 2400 - 2609'.

Set 75 sx. cement plug 2077 - 2286'. Set 75 sx. cement

plug 1493 - 1702'. Set 10 sx cement plug at surface.

Cut off wellhead - set dry hole marker and cleaned location.

18. I hereby certify that the foregoing is true and correct

SIGNED

Alvin R. Mandy

TITLE

Field Foreman

DATE

2-23-78

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

USGS(4) NMOCC(3) The Navajo Tribe-GLE-ARM-JHP