orm 3160-5 June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

1	førm approved
	Budget Bureau No. 1004-013.
RECEIVE	Expires: March 31, 1993
DI M	5. Lease Designation and Serial No.

ECEIVE	\square		Expires:	March	31, 199)3
BLM	5.	Lease	Designat	ion and	Serial	ì

Dispose Water

(Note: Report results of multiple completion on Well

APR 08 19911

OIL CON. DIV.

1 DIST. 3

BLM	3. Lease Designation and Sei
	14-20-60-1431

	BLI	
Do not use this form for proposals to d	AND REPORTS ON WELLS rill or to deepen or reentry to a different reservoi R PERMIT—" for such proposals	14-20-603-1431 5. Iffindian, Allottee or Tribe Name
SUBMIT	7. If Unit or CA, Agreement Designation	
Type of Well Oil Well Well Other	8. Well Name and No.	
Name of Operator Texaco Inc. Address and Telephone No.	Navajo Allottees "\mathcal{T}" 2 9. API Well No.	
3300 N. Butler, Farmington N.M. 87401 (505)325-4397 Location of Well (Footage, Sec., T., R., M., or Survey Description)		30-045-21744 10. Field and Pool, or Exploratory Area Basin Dakota
1740 FSL & 1500 FWL NE/SW, Sec. 14 T25N-R11W		11. County or Parish, State San Juan
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REP	ORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
Subsequent Report	Recompletion Plugging Back	New Construction Non-Routine Fracturing
Final Abandonment Notice	Casing Repair Altering Casing	Water Shut-Off Conversion to Injection

Completion or Recompletion Report and Log form.) Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texaco Inc. proposes to perform the following on the subject well:

MIRUSU, NDWH, NUBOP,

POOH w/ production equipment.

RIH w/ tbg, RBP, & pkr. Set RBP @ 5850'. Press. test csg to 1000 psi.

Perform necessory casing repairs.

RU wireline & run GR-CBL-CCL-TEMP from TOC to surface.

Perf squeeze holes above TOC & attempt to circulate to surface.

Drill out cmt & press test csg to 1000 psi.

RIH w/ production equip. NDBOP. NUWH.

RDMOSU. Return well to production. Leave bradenhead open for 14 days to allow trapped gas to escape. Shut bradenhead in for 14 days. Perform bradenhead test.

erbal approval recieved from Wayne Townsend of BLM, by Darren Segrest on 1-25-91.

		Control of the Contro
		ADDIONETO
I hereby certify that the foregoing is true and correct.		MINISTER
Signed Clan U. Kleier	Area Manager	Date 3/07/91
(This space for Federal or State office use)		
Approved by	Title	Date APR 0.3 1991
Conditions of approval, if any:		
	NMOCD	Ken Teuncoul
: 18 U.S.C. Section 1001, makes it a crime for any person know epresentations as to any matter within its jurisdiction.	vingly and willfully to make to any department or agency of the	united States any false, fictitious or fraudulent statements
	*See instruction on Reverse Side	agramma in a compression of the former and a section of the first of t