

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	
				TOP	MEAS. DEPTH
Ojo Alamo	1175'	1352'			
Fruitland	1714'	1985'			
Pictured Cliffs	1985'	2085'			
Cliffhouse	3570'	3598'			
Menefee	3598'	4370'			
Point Lookout	4370'	4600'			
Gallup	5448'	5988'			
Dakota	6354'	TD			

38. GEOLOGIC MARKERS