

F

30-045-28151

08-21-90

F. Loc. 1750/S; 1845/W Elev. 6433 GL Spd. Comp. TD PB  
 Cu. ft. Cu. ft. Cu. ft.  
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. I. @  
 Csg. Perf. Prod. Stim. T Gas  
 R  
 A  
 N  
 S  
 BO/D Grav. 1st Del. Gas  
 I.P. MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

TOPS	NIID	X	Well Log	TEST DATA						
Ojo Alamo	C-103		Plat X	Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland	C-104		Electric Log							
Fruitland			C-122							
Pictured Cliffs	Ditr		Dfa							
Chacra	Datr		Doc							
Cliff House	Hoxen									
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										

Acres W/320

P  
o  
o

BasinFrCoal Co. SJ S 14 T 25N R 11W U K Oper. Giant Explor. &amp; Prod. Le Buena Suerte 14K Co. No. 1

Buena Suerte 14K Com #1

K-14-25N-11W

Giant Explor. &amp; Prod.



# United States Department of the Interior

## BUREAU OF LAND MANAGEMENT

Farmington Resource Area

1235 Laplata Highway

Farmington, New Mexico 87401 NOO-C-14-20-5579 et al. (WC)  
3162.3-1 (019)



IN REPLY REFER TO:

Giant Exploration & Production Company  
P.O. Box 2810  
Farmington, NM 87499

OCT. 16 1991

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- ✓ 1. 1 Bisti Coal 27 Com, sec. 27, T. 25 N., R. 12 W., San Juan Co., NM  
lease NOO-C-14-20-5579.
- ✓ 2. 1 East Bisti Coal 31, sec. 31, T. 25 N., R. 11 W., San Juan Co., NM  
lease NM-76857.
- ✓ 3. 331 Carson Unit 23, sec. 23, T. 25 N., R. 12 W., San Juan Co., NM  
lease SF-078067.
- ✓ 4. 1 Buena Suerte 14K Com, sec. 14, T. 25 N., R. 11 W., San Juan Co., NM  
lease 14-20-603-1431.
- ✓ 5. 323 Carson Unit 20, sec. 20, T. 25 N., R. 11 W., San Juan Co., NM  
lease SF-078061.

As discussed with Earlene Bickford of your company on October 10, 1991 the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller  
Chief, Branch of Mineral Resources

Enclosures

cc:  
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410  
BIA, Window Rock

# ABANDONED LOCATION

