

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

MYCO INDUSTRIES, INC

3. Address and Telephone No.

P O BOX 840, ARTESIA, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2490' FSL & 1780' FWL Sec. ^K34-T25N-R13W

5. Lease Designation and Serial No.

NM-57453

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

LY FEDERAL #1

9. API Well No.

30-045-29113

10. Field and Pool, or Exploratory Area

BASIN-FRUITLAND COAL

11. County or Parish, State

SAN JUAN, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other PLUG & ABANDON

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

10/10/96 Notify BLM 24-hr notice P/A.

10/11/96 Rig up pulling unit. Remove Highland pump rotating assembly from wellhead. Pull out of hole with polish rod, spacer, 36 sucker rods and rotating stator for pump. Nipple up BOP on casing. Pull out of hole with 28-jts 2-3/8" tubing Tally=923.82" and pump barrel assembly. Make up Watson Packer CIBP on end of tubing and go in hole. Set CIBP at 825'. (50' within top perforation by BLM). Shear off CIBP, tag CIBP and rig up Cementers, Inc. Pressure test CIBP and csg to 500# with no leakoff. Close BOP and establish circulation with 11 bbls. Mix and pump 75 sxs Class "G" Neat cement (Yld--1.17 ft 3 @ 15.8#/gal). Circulated cement from 825' to surface. Pull out of hole laying down tubing. Nipple down BOP. Cut off wellhead. Top casing off with cement. Install dry hole marker. Empty tank of water. Rig down and release pulling unit. Cut off anchors. Fill in cellar. Release all rental equipment. Pulled out 36-bbls water from stock tank and hauled to disposal.

10/14/96 Prepare to rip & seed location per BLM requirements. Rehab work to be finished by Calder Service, Farmington, NM. Calder will notify BLM for final inspection.

CERTIFIED RETURN: P 387 147 985

14. I hereby certify that the foregoing is true and correct

Signed Selda Mares

Title ENGINEERING TECHNICIAN

Date 10/17/96

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

APPROVED

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

Chip Harlander
for DISTRICT MANAGER