

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB NO. 1004-0135  
Expires: November 30, 2000

**SUNDRY NOTICES AND REPORTS ON WELLS**

*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

5. Lease Serial No.

SF 080375

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or N

8. Well Name and No.

Sheets C 8

9. API Well No.

30-039-06210

10. Field and Pool, or Exploratory Area  
Ballard PC

11. County or Parish, State

Rio Arriba NM

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

ENERGEN RESOURCES CORPORATION

3a. Address

2198 Bloomfield Highway, Farmington, NM 87401

3b. Phone No. (include area code)

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

790' FSL, 1485' FWL, Sec. 31, T26N, R7W, N.M.P.M.

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

**TYPE OF SUBMISSION**

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

**TYPE OF ACTION**

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☒ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomplate in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

7/13/01 MIRU. ND wellhead, NU BOP. TOH laying down 1-1/4" tubing and 1" line pipe.

7/14/01 TIH with 5-1/2" RBP and packer, set RBP at 2674'. Test casing to 3000 psi - OK. Reset RBP at 2750' and test to 1000 psi. TOH with tubing and packer. RU Computalog and run GR/CCL. Perforate Pictured Cliffs from 2682'-2704' w/2 SPF. RD Computalog. ND BOP, NU frac valve.

7/21/01 RU Halliburton. Spearhead 1000 gals 15% HCL, Frac with 20,414 gals 70 Q foam and 70,439# 20/40 sand. RD Halliburton. Flow well on 1/4" choke.

7/23/01 ND frac valve, NU BOP. TIH with retrieving tool, latch onto RBP and TOH. TIH with 4-3/4" mill.

7/24/01 Clean out to 2784'. TOH laying down 2-3/8" tubing and mill. TIH with 1-1/2" production tubing, land at 2690', seating nipple at 2657'. ND BOP, NU wellhead. RDMO.

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Don Graham

Title

Drilling/Completion Foreman

Date 8/7/01

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

ACCEPTED FOR RECORD

NOV 05 2001

FARMINGTON FIELD OFFICE