UNITED STATES

DEPARTMENT OF THE INTERIOR RECEIVED BUREAU OF LAND MANAGEMENT M MAIL ROUM

		D1.11.1			
Su	ndry Notices	THE BOATS OF THE	1681 AH 1:03		
	DECE		MANUTON, NM	5.	Lease Number SF-080670
. Type of Well	130	TO TO THE	g min - O	6.	If Indian, All. or Tribe Name
	0/3/3			7.	Unit Agreement Name
Name of Operator MERIDIAN ©IL					San Juan 27-4 Unit
	-5 Ot			8.	Well Name & Number San Juan 27-4 U #89
PO Box 4289, Farmir	igton, NM 87	499 (505) 326-970	00	9.	API Well No. 30-039-20828
Location of Well, Fo	ootage, Sec., Sec.30, T-27	T, R, M -N, R-4-W, NMPM			Field and Pool Tapacito Pictured Cliff
,				11.	County and State Rio Arriba Co, NM
2. CHECK APPROPRIATE I	SOX TO INDICA	TE NATURE OF NOT	ICE, REPORT,	OTHER	DATA
Type of Submission		Type of	Action		
X Notice of In	ntent	Abandonment Recompletion	Change New Con	struct	tion
Subsequent I	Report	Plugging Back Casing Repair	Water S	hut o	
Final Abando	onmentX	Altering Casing Other - Restor			o Injection
13. Describe Proposed	d or Complete	ed Operations			
production pressure was shut due to co	on. The well information in due to hi	will be obtained. gh line pressure 200-250 psi, giv	an Echometer . The well wil .(350 psi). Th	fluic ll the ne lin	Cliffs well to delevel and bottomhole en be swabbed. The well de pressure has dropped delieve the well is
	11-1 the 5-	regoing is true a	and correct		
		(JME3) Title Regul		trato	r_Date 10/17/95
(This space for Federa APPROVED BY		ffice use)Title	Da	ite _	
CONDITION OF APPROVAL,	ıı any:			ΑP	PROVED
			, -		77 1 8 1995

NMOCD