



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**GARY E. JOHNSON**

Governor

**Jennifer A. Salisbury**

Cabinet Secretary

**Lori Wrotenbery**

Director

**Oil Conservation Division**

December 6, 2001

Dolores Silseth  
Burlington Res. O&G Co.  
PO Box 4289  
Farmington NM 87499

Re: San Juan 27-4 Unit # 124, K-08-27N-04W, API 30-039-21031

Dear Dolores:

The 2001 Packer Leakage Test on the referenced well indicates the pressure in the upper zone had not stabilized, number 3 on the back of the Northwest New Mexico Packer-Leakage Test Form

...Both zones shall remain shut-in until the wellhead pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.

You are hereby directed to conduct a Packer Leakage test to show separation of the zones prior to January 1, 2002.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely,

Charlie T Perrin  
Deputy Oil & Gas Inspector  
cperrin@state.nm.us

CTP/mk

CC: BLM  
CTP  
Well File