

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

SF-079366

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

RINCON UNIT

8. Well Name and No.

RINCON #254

9. API Well No.

10. Field and Pool, or Exploratory Area

Basin Fruitland Coal

11. County or Parish, State

Rio Arriba, New Mexico

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

UNION OIL COMPANY OF CALIFORNIA

3. Address and Telephone No.

P.O. BOX 2620, Casper, WY 82602-2620 (307) 234-1563 Ext. 116

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec. 20, T27N-R6W

Surf. 1419' FNL, 794' FEL; TD 1411' FNL, 1648' FEL

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Union Oil Company of California proposes to plug and abandon the Rincon Unit Well No. 254 according to the attached procedure.

RECEIVED  
SEP 21 1995  
OIL CON. DIV.  
DIST. 3

RECEIVED  
BLM MAIL ROOM  
20 AUG 29 AM 9:03  
070 FARMINGTON, NM

14. I hereby certify that the foregoing is true and correct

Signed

*Jim Benson*

Title Drilling Superintendent

Date 8-25-95

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

AS AMENDED

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States a false and fraudulent statement or representations as to any matter within its jurisdiction.

\*See instruction on Reverse Side

DISTRICT MANAGER

NMOCD

RINCON UNIT WELL #254  
P & A PROCEDURE

- 1) Test deadmen. MIRU service rig and equip. Kill well if necessary. ND tree. NU BOP's.
- 2) Tag ETD. Clean out if necessary. Strap out of hole w/2-3/8" tbg. TIH w/5½" cmt retainer on 2-3/8" tbg to 3300'. Pump thru retainer. Set retainer @ ±3300'.
- 3) Squeeze Fruitland perfs 3458'-3468' w/50 sx Class "B" cmt containing 2% Cacl. Sting out of retainer and spot 25 sx same cmt from 3300'-3090'. PU w/tbg to 3090'. Circ tbg and wellbore clean (PLUG #1).
- 4) POOH, laying down 2-3/8" tbg to 2360' (NOTE: Top of Ojo Alamo at 2304'). Pump and spot 25 sx same cmt from 2360' to 2145'. (PLUG #2).
- 5) POOH, laying down 2-3/8" tbg to 1390' (NOTE: Top of Nacimiento at 1336'). Pump and spot 25 sx same cmt from 1390' to 1175' (PLUG #3).
- 6) POOH to ±120'. Pump and spot 20 sx same cmt from 120' to surface. (PLUG #4). Lay down tbg.
- 7) Cut off csg 4' below GL. Install dry hole marker. Clean up and restore location.

RINCON UNIT # 254 BASIN FRUITLAND COAL  
UNIT H, 20, 27N, 6W, RIO ARRIBA COUNTY, NM

