

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
UNION OIL COMPANY OF CALIFORNIA

3. Address and Telephone No.
3300 N. BUTLER, SUITE 200, FARMINGTON, NM 87401 (505)326-7600

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1140' FNL & 875' FWL
SEC. 21, T27N, R6W

FORM APPROVED
Budget Bureau No. 1004-0133
Expires: March 31, 1993

5. Lease Designation and Serial No.
SF-079366

6. If Indian, Allottee or Tribe Name
N/A

7. If Unit or CA, Agreement Designation
RINCON UNIT

8. Well Name and No.
RINCON UNIT #180M

9. API Well No.
30-039-25186

10. Field and Pool, or Exploratory Area
BASIN DK/BLANCO MV

11. County or Parish, State
RIO ARRIBA, NEW MEXIC

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other Notification of status of Dakota formation.	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The initial completion attempt of the Dakota formation in the Rincon Unit No. 180-M was unsuccessful. The well would not sustain continuous flow. A bottomhole pressure bomb was run for a 7 day buildup. The buildup is currently being evaluated to develop procedures for a second completion attempt.

RECEIVED
OCT 22 1992
OIL CON. DIV.
BLM

RECEIVED
BLM
92 OCT 14 AM 10:42
019 FARMINGTON, N.M.

14. I hereby certify that the foregoing is true and correct

Signed [Signature] Title FIELD SUPERINTENDENT Date 10/13/92

(This space for Federal or State office use)

Approved by _____ Title _____

Conditions of approval, if any: _____

ACCEPTED FOR RECORD

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side
NMOCB
FARMINGTON RESOURCE AREA
BY [Signature]