

16	2641. 65	N 89° 09' W	2641. 65	
				<b>Dakota</b>
16	159. 74	52	156. 24	92
2657. 16	AC ±	2601. 52	AC ±	2548. 92
N 0° 22' W	2646. 51	<div style="border: 2px solid black; padding: 5px; transform: rotate(-5deg); display: inline-block;"> <b>RECEIVED</b>  <b>FEB - 3 1995</b>  <b>OIL CON. DIV.</b>  <b>DIST. 3</b> </div>		2646. 51
16	159. 44	52	156. 07	92
2657. 16	AC ±	2601. 52	AC ±	2548. 92
S 0° 27' 53" E	2653. 20	S 84° 45' W	2653. 20	<div style="border: 1px dashed black; padding: 10px; display: inline-block;"> <b>Tacita</b> </div>

**17 OPERATOR CERTIFICATION**

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief

Signature Jim Benson

Printed Name Drilling Superintendent

Title 2-2-95

Date

**18 SURVEYOR CERTIFICATION**

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

September 7, 1993

Date of Survey

Signature and Seal of Professional Surveyor:

NEW MEXICO

REGISTERED PROFESSIONAL LAND SURVEYOR

9672

Cecil B. Tullis

Certificate Number 9672