Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

SF 079298

dell	AND REPORTS ON WELLS I or to deepen or reentry to a different reservoir. PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA. Agreement Designant
		RINCON UNIT
1. Type of Well Oil Gas Well Well Other		8. Well Name and No. #177E
2. Name of Operator UNION OIL COMPANY OF CALIFORNIA	· ·	9. API Well No.
3 Address and Telephone No.	201 1562 East 116	30-039-25491 10. Field and Pool, or Exploratory Area
P.O. Box 2620, Casper, WY 82602 (507) 254 1505		Basin Dak/S. Blanco
4. Location of Well (Footage, Sec., T., R., M., or Survey Des	capaon)	11. County or Parish, State P.C.
1825' FSL & 1505' FEL (NW SE) Sec. 13, T27N-R7W		Rio Arriba, NM
OUECK APPROPRIATE BOXIS	TO INDICATE NATURE OF NOTICE, REPORT	RT, OR OTHER DATA
	TYPE OF ACTION	
TYPE OF SUBMISSION	Abandonment	Change of Plans
Nouce of Intent	Recompletion	New Construction
X Subsequent Report	Plugging Back	Non-Routine Fracturing Water Shut-Off
(14 Subseduery sealogy	Casing Repair	Conversion to Injection
Final Abandonment Notice	Altering Casing Other WEEKLY SUMMARY	Dispose Water
	pertinent details, and give pertinent dates, including estimated date of starting depths for all markers and zones pertinent to this work.)	(Note: Report results of multiple completion of Completion or Recompletion Report and Log
	DECENVED JUL 2 4 1995 OIL CON. DIV. DIST. 3	RECEIVED BLM 95 JUL 19 PH 2: 09
	e de la companya de l	
14. I hereby certify that the foregoing istatue and correct Signed Pull REUSON	Title Drilling Superintendent	Date
(This space for Federal or State office use)		Date
Approved by	ACCEPTED FOR RECORD	
1001 mares it a crime for any person	knowingly and willfully to make to any department or agency of the United	States any false figurations or fraudulent sta
Title 18 U.S.C. Section 1001, makes it a claim or representations as to any matter within its jurisdiction.	*See instruction on Reverse Side	UI NO 1005

RINCON UNIT #177E RIO ARRIBA CO., N.M.

WEEKLY SUMMARY

- 7-10-95 Drill from 400' to 1914' in 22.25 hours, rop68ft./hr wob 20/25 rpm 75/85. Hole in good shape on conn.
- 7-11-95 Drill to 2265' lost 300# pump pressure. POOH, Did not find a hole or reason for pressure loss. FU new bit TIH to 2180, Wash and ream 85' to bottom. Drill to 2459, ran survey, 1.5deg. Drill to 2698 in 11.75 Hrs. avg.37'/hr. 25/30 wob ,85rpm. Now on bottom drilling.
- 7-12-95 Drilled from 2698 to 3477 779' in 22.5 Hrs. avg. 34.6'/hr. 80rpm, 35/40wob.now on bottom drilling.
- 7-13-95 Drilling from 3477 to 4199' 722' in 233/4 hours. 30.4'/hr. wob35/40 rpm80, Now on bottom drilling.
- 7-14-95 Drilled to 4447' Torque converter went out on #1 engine. Pooh, change out torque converter, tih, wash 45' to bottom. Drill to 4467 avg.rop 19'/hr. wob35/40 rpm70/80. Kevin Schneider with BLM Inspected rig, all was ok, needed to remember to record SPR, and Pit Drills on IADC reports. Survey on trip was a miss-run.
- 7-15-95 Drilling from 4467' to 4956' 489' in 23.5 hrs avg. rop 20.8ft./hr. Pumped 3-10bbl magna-fiber sweeps. Now on bottom drilling @ 5030'
- 7-16-95 Drilled to 5090' Bit torqued up, Pooh, change bit, service rig, work blind and pipe rams, tih, to 4990' wash and ream 100' fill to bottom. Drill from 5090' to 5335 in 12 hours, avg.rop 20.4'/hr. 40wob. 70/80rpm.

Pumped 3 10bbl. Magma-fiber sweeps.

7-17-95 Drill from 5335 to 5787, 452' in 21 hours. avg.21.5'ft/hr.rpm70/80 wob 35/40.

Made connection @ 5786 drilled 1 ft. and lost complete returns. Pumped premix tank and partial pits when rotary torque started to increase. Pulled 15 tank and partial pits when rotary torque started to increase. Pulled 15 stands, 1st.9 stands pulled 100,000 over, came free, now rotating, and mixing loss circulation material. Lost est. 550 BBLS.

While drilling pumped 3-10 bbl magma-fiber sweeps.