

37 SUMMARY OF POROUS ZONES: (Show all Important zones of porosity and contents thereof; cored intervals; and all drill -stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
Fruitland Coal	2968'	3018'	Gas
Pictured Cliffs	3018'	3218'	Gas
Mesa Verde	4708'	5638'	Gas & Oil
Dakota	7458'	7650'	Gas & Oil

38. GEOLOGIC MARKERS			38. GEOLOGIC MARKERS		
NAME	TOP		NAME	TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH		MEAS. DEPTH	TRUE VERT. DEPTH
San Jose	Surface		Point Lookout	5288'	
Ojo Alamo	2318'		Mancos	5638'	
Kirtland Shale	2418'		Tocito Sand	6853'	
Pictured Cliffs	3018'		Dakota	7458'	
Lewis Shale	3218'				
Cliff House	4708'				