Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No

Use "APPLICATIO	ICES AND REPORTS ON WELLS to drill or to deepen or reentry to a different res N FOR PERMIT-" for such proposals	6. If Indian, Allottee or Tribe Name
OUI	NATIN TOICHOATE	7. If Unit or CA, Agreement Designation
SUBMIT IN TRIPLICATE 1. Type of Well Oil Gas Gas		Rincon
Well Well Other Name of Operator		8. Well Name and No. Rincon Unit #162
Union Oil Company of California		9. API Well No.
Address and Telephone No.		30-039-82372
P. O. Box 671Midland, TX 79702	915 685-7607	10. Field and Pool, or Exploratory A.ea
Location of Well (Footage, Sec., T., R., M., or Sur	vey Description)	Blanco S-PC
1650' FSL & 1850' FWL Sec. 27, T27N, R6W		11. County or Parish, State
		Rio Arriba, NM
CHECK APPROPRIATE B	OX(s) TO INDICATE NATURE OF NOTICE, REP	
TYPE OF SUBMISSION	TYPE OF AC	
☑ Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
☐ Subsequent Report ☐ Final Abandonment Notice	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
	☐ Altering Casing	Conversion to Injection
	Other	Dispose Water (Note: Report results of multiple completion on W-ill
SEE ATTACHED PROCEDURE DECE		BEIVEN
	M G P	50 1 1 1000
	Į.,	EB 1 1 1978
	6 <u>11</u>	EB 1 1 1978 COM. DUV.
	OIL '	EB 1 1 1978 (COM) (COM) (COM) (COM) (COM) (COM)
signer Mallatte Deeso		EB 1 1 1998 (Co) (Co) (Co) (Co) (Co) (Co) (Co) (Co)
4. I hereby certify that the foregoing is true and cor Signed Alberta Dela Society (This space for Federal or State office use) Approved by/S/ Duane W. Spence Conditions of approval, if any:	Title Regulatory Clerk	्राह्मका है। इ.स.
Signed Nation Decision This space for Federal or State office use) Approved by /S/ Duane W. Spence Conditions of approval, if any:	Title Regulatory Clerk Title	Date 02/02/98 Date FEB - 2 1998
This space for Federal or State office use) Approved by /S/ Duane W. Spence Conditions of approval, if any: itle 18 U.S.C. Section 1001, makes it a crime for an	Title Regulatory Clerk Title	Date 02/02/98 Date FEB - 2 1998



By: Mike Phillips

PROCEDURE:

- 1. MIRU P&A Service Unit and cement Equip. Perform rig inspection. Hold safety meeting.
- 2. Blow well down. Rig up and Kill well if necessary. ND Tree. NU BOP & function test. PU & RIH w/OE'D 1.25" WS to 3250'. RU & CIRC well w/MLB. RU and spot 25 sx class "C" cement + 2% CACL from 3250-2400'. PU to 2600'. Reverse clean. Plug #1:(2600-3250') Kirtland Fruitland, and PC Tops. TOH laying down WS. SD WOC.
- 3. While waiting on cement, ND WH. NU on 2-7/8" casing. Est free pt by stretch. RU WL and RIH and tag TOC @ 2600'. POH w/ WL.
- 4. Press test 2-7/8" from surf to 2600'. RU and RIH w/ jet cutter on WL. Cut tubing @ ±2600'. Circulate hole with approved plug mud.
- 5. Spot 50 sx class "C" cement from 2543-2348'. *Plug #2:(2348-2543'.) Ojo Alamo.*
- 6. PUH to 300'. Spot 80 sx class "C" cement from 300 to surface. *Plug* #3:(Surface to 300'). POH LD TBG.
- 7. RD Unit and Equip. Dig out wellhead w/backhoe. Cut-off head and weld-on P&A marker as per BLM specifications. Dig –out and remove anchors. Backfill and clean & level location.



