Form 3 (June 19	
--------------------	--

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

	FORM	4 APPR	OVED	
-	Bilgol Bu	tau No.	1004-01	Ľ
/	Expires:	March	31, 1993	

7	witer per	₩ F0.	IWA	-013
	Expires:	March	31, 6	193
	Decises			

			 . =
S. Ka	se Des	gando	3
SF	078	1155	

Change of Plans

Completion or Recompletion Report and Log form.)

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - for such proposals

7. If Unit or CA, Agreement Designation

SUBMIT	IN TRIBLICATE DE C = 2 1993	
1. Type of Well		West Bisti Unit
ON Ges X Other Water I	njection Well	8. Well Name and No.
2. Name of Operator		West Bisti Unit 150
Dugan Production Corp.	5167. 3	9. API Well No.
3. Address and Telephone No.		30-045-05622
P.O. Box 420, Farmington,		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey D	escription)	*Bisti Lower Gallup
1980' FNL - 1980' FEL		11. County or Parish, State
Sec. 35, T26N, R13W, NMPM		San Juan, NM
CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SURMISSION	TYPE OF ACTION	l

	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	X Other Test-repair or plug	Dispose Water
		(Note: Report results of multiple completion on Well

Absadooment

Determine possibility of repairing casing or plugging as follows:

- 1. Run packer and isolate holes in casing. If casing can be repaired, proceed with return to injection. If unrepairable, plug.
- 2. Spot 100' Class B cement plug across Gallup top at 4895'.
- 3. Perforate 50' below Mesa Verde top at 2580' and spot 100' Class B cement plug inside and outside production casing.
- 4. Perforate 50' below Pictured Cliffs top at 1321'. Spot Class B + 4% gel cement plug to cover Fruitland top at 860' ≥inside and outside production.
- 5. Perforate 50' below surface casing at 214'. Cement to surface with Class B + 4% gel cement.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

 NMEED appu	e/s/ 13	also required	
I hereby certify that the foregoing is true and correct Signed Jole Clevand	Title	Operations Manager	
(This space for Federal or State Office use) Approved by Conditions of approval, if any:	Title		Date
			APPROVED

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any Misc. Vicustoss or traidelent statements or representations as to any matter within its jurisdiction

^{13.} Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 La Plata Highway Farmington, New Mexico 87401

Arta	chment	to Notice	Ωf
Δ LWI	L.H.H.C.H.	ID MOHEE	OI

Re: Permanent Abandonment

Intention to Abandon

Well: 150 West Bistillair

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
- 2. Mike Flanken with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made (when applicable):

1.) Spot Gallup cement plug from 5038' to 4680'

Plus & Linear feet excerc. (Gallup Top 4730')

Tag Toc.

2.) Move Mecavede plug. Perforate D 2030' and

Place a cement plug from 2030' to 1930' insidex':

outside the casing plus 1002 excerc. (MU Top D 1980')

3.) Fruit and Top D 990', PC Top D 1250' - Required

Plug inside Loutside cowing from 1300' to 950'.

Office Hours: 7:45 a.m. to 4:30 p.m.