

Submit 3 Copies
to Appropriate
District Office

3 NMOC

1 File

DISTRICT I WBU wios
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

Energy, Minerals and Natural Resources Department

Form C-100
Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30 045 05637

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

E-4501-8

7. Lease Name or Unit Agreement Name

West Bisti Unit

8. Well No.

147

9. Pool name or Wildcat

Bisti Lower Gallup

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL

WELL ☒

GAS

WELL ☐

OTHER ☐

2. Name of Operator

Dugan Production Corp.

3. Address of Operator

P.O. Box 420, Farmington, NM 87499

4. Well Location

Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line

Section 36 Township 26N Range 13W NMPM San Juan County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is intended to plug & abandon this well as follows:

- * 1.) Set a cast iron bridge plug 50' below the top of the Gallup @ ^{4800'} 4680'. Cap with 15-sx class "B" cement. ^{to 4630'}
- 2.) Perforate 50' below the Mesa Verde top (2510'). Pump ⁴⁷ 30-sx class "B" cement to cover 100' inside and outside casing.
- 3.) Perforate 50' below Pictured Cliffs top (1240'). Pump ¹⁰⁰ 70-sks class "B" to cover Fruitland top ^{1075' oil} (1060') and Pictured Cliffs top.
- 4.) Perforate at 50' below surface casing at a depth of 320'. Pump 95 sks class "B" to fill casing ^{1111' plug} and annulus to surface.
- 5.) Set dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Operations Manager

DATE 4/12/96

TYPE OR PRINT NAME

Gary Brink

TELEPHONE NO.

(This space for State Use)

APPROVED BY

Johnny Robinson

TITLE

DATE

APR 18 1996

CONDITIONS OF APPROVAL, IF ANY:

* As Noted Above

Notify OCD in time to witness