

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. NAME OF OPERATOR Robert L. Bayless	3. ADDRESS OF OPERATOR P.O. Box 168, Farmington, NM 87499	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 1980' FEL	5. LEASE DESIGNATION AND SERIAL NO. 14-20-603-5034	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo	7. UNIT AGREEMENT NAME SINNY-2 PH12:56	8. FARM OR LEASE NAME Navajo Tribal "U"	9. WELL NO. 2	10. FIELD AND POOL, OR WILDCAT Tocito Dome Penn. "D"	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 21, T26N, R18W	12. COUNTY OR PARISH San Juan	13. STATE NM
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5705' RKB											

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	(Other) _____

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS* (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well plugged and abandoned per attached daily report and with BLM witness.

RECEIVED
MAY 5 1991
OIL CON. DIV.
DIST. 3

Approved as to plugging of the well by a
liability under bond in relation with
surface restoration is hereby stated.

18. I hereby certify that the foregoing is true and correct

SIGNED

Tom McCarthy
Tom McCarthy

TITLE Petroleum Engineer

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

NWOOD

*See Instructions on Reverse Side

APPROVED	
DATE	5-1-91
MAY 09 1991	
DATE	
AREA MANAGER FARMINGTON RECORDS AREA	

NAVAJO TRIBAL U NO. 2
PLUGGING AND ABANDONMENT

4/26/91 Move in Bayless Rig #6. Nipple up BOP's. Trip in with 2 3/8" tubing. Tag obstruction at 4275' (Bridge Plug). Received approval from Wayne Townsend at BLM to modify plugging and abandonment procedure.

4/27/91 Pressure test casing. Would not hold. Wait on packer. Trip in with packer. Pressure test casing; would not hold. Spot cement plugs as follows consisting of Class B,

3377' - 4265'	60 sacks (71 cf)
WOC 3 1/2 hrs. tagged cement at 3375'.	
2680' - 2796'	25 sacks (30 cf)
1980' - 2185'	25 sacks (30 cf)
1430' - 1552'	25 sacks (30 cf)
Surface - 157'	25 sacks (30 cf)

Spotted 39 bbls. 9 PPG mud between plugs, (219 cf).

4/28/91 SI FS

4/29/91 Cut off wellhead. Run 63' of 1" tubing down 13 3/8 - 8 5/8" annulus. Cemented with 35 sx (41 cf). Circulate cement to surface. Run 63' of 1" tubing down 8 5/8 - 4 1/2" annulus. Cemented with 14 sacks (17 cf). Circulate cement to surface. Rig down. Set plugging and abandonment marker. Pit will be backfilled when dry.