

Form 100-10
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

ADMIT INSTRUCTIONS
(Other instructions on re-
verse side)

Budget Form No. 100-1001

5. LEASE DESIGNATION AND SERIAL NO.

SF - 075433

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Mawson

9. WELL NO.

10

10. FIELD AND POOL, OR WILDCAT

Belmont District Office

11. SEC., T., R., M., OR BLK. AND

SURVEY OR AREA

Sec. 30, T-26N, R-6W
Hillman

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

1.

OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Leasch Union Production Company

3. ADDRESS OF OPERATOR

P.O. Box 200, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

900 ft. from the South line and 900 ft. from the West line.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6400' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Rigged up L & H Ventures pulling unit.

2. Pumped 20 lbs cement plug 2202', 2100'.

3. Pumped 1" tubing.

4. Shot 4 sphere holes @ 1000', ran 1" tubing to 1000' and cement. 1/36 lbs cement.

5. Pumped 1" tubing, ran 91' - 1" tubing and spotted 6 lbs plug 91' to 50'.

6. Spotted 2 lbs plug (10') @ surface and set dry hole marker.

7. We will reduce fill slope and reseed location in spring of 1977.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Superintendent

DATE 12/1/76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

