

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUMMARY NOTICES AND REPORTS

(Do not use this form for reports on wells or for reports on wells that are not in the Bureau of Land Management's custody.)

1. NAME OF OPERATOR
Chevron U.S.A. Inc., Room 11111
2. ADDRESS OF OPERATOR
P. O. Box 599, Denver, Colorado 80201

14. LOCATION NO. 15. ELEVATION (feet) above sea level

16. Check Appropriate Box To Indicate Nature of Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER INFLOW	PUMP OR ALTER Casing
FRACTURE TREAT	MULTIPLE COMPLETION
CHIEF OR SUBMIT	ABANDON*
REPAIR WELL	CHANGE PLANS

OTHER: Long term shut-in

QUALITY REPORT OF:

EXPERIENCE	REPAIRING WELL
TRAILER TREATMENT	ALTERING Casing
PRODUCTION OR ABANDON	ABANDONMENT

*This report results of multiple completion on Well
Completion or Recommendation Report and Log form

17. (a) If the well is being plugged and abandoned, include the following information: (b) If the well is being plugged and abandoned, include the following information: (c) If the well is being plugged and abandoned, include the following information:

DETAIL FOR LT SHUT IN EXTENSIONS

Chevron U.S.A. Inc. requests a one year extension of the long term shut-in status for the wells listed in the table attached. The extension is necessary due to the time required to evaluate a waterflood expansion pilot.

A detailed reservoir study of the West Bisti Unit has indicated that a substantial amount of additional oil can be recovered by revamping the waterflood. In order to determine if the additional oil can be recovered economically, a pilot waterflood expansion is expected to be completed in the First Quarter of 1988. The complete analysis of the pilot is expected to take approximately one year. Well No.'s 123, 141 and 134 have been recently shut in due to their uneconomic status. These wells could also be utilized in revamping the waterflood. A one year shut in status is requested for these wells.

Based upon the results of the waterflood expansion, these wells will be 1) utilized in revamping the complete waterflood in 1989 or 2) plugged and abandoned in 1989.

THIS APPROVAL EXPIRES 12/31/88

6 - BLM
1 - EEM
1 - WAC

1 - Contr. File

APPROVED

DATE December 9, 1987

SIGNED

DEC 24 1987

NAME

James E. Edwards

MANAGER

PERMITS & RESOURCE AREA

*See Instructions on Reverse Side

RECEIVED
DEC 30 1987

OIL CON. DIV
DIST. 3

Lease No.	Well		LT S.I.	Location	Sec., T., R.	Elevation
	No.	Type	Extension Sundry Due			
14-20-603-735-A	100	Oil Producer	1/22/88	1,980' FNL, 1,980' FEL	13-26N-14W	6357
NM-013492	102	Oil Producer	1/22/88	1,980' FSL, 1,165' FWL	18-26N-13W	6463
NM-013492	103	Oil Producer	1/22/88	660' FSL, 660' FEL	18-26N-13W	6312
NM-013492	109	Oil Producer	12/23/87	1,980' FNL, 660' FEL	20-26N-13W	6376
NM-013492	118	Oil Producer	12/23/87	660' FSL, 660' FEL	20-26N-13W	6380
SF-078091	121	Oil Producer	12/23/87	660' FNL, 1,980' FWL	29-26N-13W	6572
	123	Oil Producer		660' FNL, 1,980' FWL	28-26N-13W	6256
SF-078091	128	" "	5/19/88	1,980' FNL, 660' FWL	28-26N-13W	6320
SF-078091	132	" "	5/19/88	1,980' FSL, 660' FEL	28-26N-13W	6231
	134	" "		1,980' FSL, 660' FEL	27-26N-13W	6198
SF-081028-A	136	" "	1/22/88	660' FSL, 1,978' FEL	26-26N-13W	6205
	141	" "		660' FSL, 1,980' FEL	28-26N-13W	6276
SF-078155	146	" "	"	660' FNL, 1,980' FWL	35-26N-13W	6221
SF-078155	154	" "	"	1,980' FSL, 660' FEL	35-26N-13W	6233
SF-078155	159	" "	"	660' FSL, 1,980' FEL	35-26N-13W	6169
SF-078155	161	" "	"	600' FNL, 600' FEL	1-25N-13W	6179
SF-078155	162	" "	"	1,880' FNL, 1,980' FEL	1-25N-13W	6218
SF-078155	165	" "	"	660' FSL, 1,980' FEL	1-25N-13W	6239
	149	" "	12/87	2,310' FNL, 1,650' FEL	35-26N-13W	6230
SF-078155	153	Injector	5/19/88	1,990' FSL, 1,960' FWL	35-26N-13W	6237
SF-078091	131	Oil Producer	1/22/88	2,200' FSL, 1,400' FEL	28-26N-13W	6210
SF-078091	138	Oil Producer	1/22/88	990' FSL, 990' FEL	27-26N-13W	6209