


*well file*



TENNECO OIL COMPANY • P. O. BOX 1714 • 835 SECOND AVENUE • DURANGO, COLORADO

June 11, 1962

New Mexico Oil Conservation Commission  
1000 Rio Brazos Road  
Aztec, New Mexico

Gentlemen:

Subject: W. O. Berger #4, Section 22, T26N,  
R11W, San Juan County, New Mexico

In March, 1962, the annual packer leakage test was conducted on the subject well. A decrease in Gallup shut-in surface pressure was observed while producing the lower Dakota side. No decrease was observed in Dakota shut-in pressure while producing the Gallup. It was requested that this test be re-run with a pressure bomb in the upper completion while flowing the Dakota zone. This was done on May 21, 1962. The Gallup bottom hole pressure did not decrease while flowing the Dakota in this test. This additional test data indicates that communication does not exist between the two zones.

Very truly yours,

TENNECO OIL COMPANY



L. B. Plumb

District Production Superintendent

MCM:pk

