

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
-----

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	-----
<b>Rocanville Corporation</b>	8. Farm or Lease Name
3. Address of Operator	<b>Riddle Trust</b>
<b>1126 Mercantile Securities Bldg. Dallas, Texas 75201</b>	9. Well No.
4. Location of Well	<b>1</b>
UNIT LETTER <b>M</b> <b>615</b> FEET FROM THE <b>South</b> LINE AND <b>255</b> FEET FROM	10. Field and Pool, or Wildcat
THE <b>West</b> LINE, SECTION <b>18</b> TOWNSHIP <b>26N</b> RANGE <b>13W</b> NMPM.	<b>Bisti Lower Gallup</b>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
<b>6486' D.F.</b>	<b>San Juan</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

REMEDIAL WORK	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

ALTERING CASING	<input type="checkbox"/>
PLUG AND ABANDONMENT	<input type="checkbox"/>
OTHER	<input type="checkbox"/>


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Plug and abandon well as instructed.**

**Attempt to pull 5 1/2" casing. Squeeze perforations 5291-5301. Place 50' plug in; 50' plug out of casing stub. Place plugs at 2250-2350 and 1600-1700. Place plug and regulation marker at surface.**

**If casing cannot be pulled, squeeze perforations 5291-5301 place plug and regulation marker at surface.**

\* Subject to placement of a 50' cement plug outside of the 5 1/2" casing at a depth above 1645 & below 500' in the event casing is LOST in the hole



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. A. R. J. TITLE Agent DATE 3-20-67  
APPROVED BY Emmye Amed TITLE Sup Dist III DATE 3-29-67  
CONDITIONS OF APPROVAL, IF ANY:

