## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Sente Fe
Lease No	073835
Unit	Hosell

Petroleun Engineer

RELIVE

SUNDRY NOTICES AND REPORTS ON WE OIL NOTICE OF INTENTION TO DRILL SUBSEQUENT REPORT OF WATER SHUT-OFF. SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING NOTICE OF INTENTION TO CHANGE PLANS\_\_\_\_\_ SUBSEQUENT REPORT OF ALTERING CASING. NOTICE OF INTENTION TO TEST WATER SHUT-OFF..... NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL. SUBSEQUENT REPORT OF REDRILLING OR REPAIR. SUBSPOUENT REPORT OF ABANDONMENT NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO PULL OR ALTER CASING..... SUPPLEMENTARY WELL HISTORY..... NOTICE OF INTENTION TO ABANDON WELL ... (INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA) August 28 Well No. 37 is located 990 ft. from the line of sec. 7 M. M. P. M. III RE Section 7 (Meridian) (14 Sec. and Sec. No.) Rio Arriba Blanco - La Plata (County or Subdivision) (State or Territory) ground DETAILS OF WORK (State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work) Sped August 27, 1951. Total death 309'. Rem mine joints 9-5/8" J-55 36 1b. (289') set at 301' with 150 sechs regular est circulated to surface Held 500 lbs. for 30 minutes. I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced. Company SAN JUAN PRODUCTION COMPANY

U. S. GOVERNMENT PRINTING OFFICE 16-8437-4

Address 102 Borth Court Avenue

Farmington, New Mexico