Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB 1:004-0135

(Dires: November 30, 200

Expires: November 30, 2000

If Indian, Allottee or Tripe Name

<b>.</b>	Lease Serial No.			
	SF-078569			

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

and induited Well	. 030 / 0//// 3/00-	o (AFD) for sucii proposa	iis.		
- <u> </u>	RIPLICATE - Oth	er Instructions on revers	e side	7. If Unit or CA/Agreer	
Type Of Well     Oil Well    Gas W.	ell 🔀 Oth	er 🔲:	APR 2001	8. Well Name And No SAN JUAN	28-7 UNIT #228
2. Name Of Operator  CONOCO INC.			CALCODE DE Z Disters (23)	9. API Well No. 30-039-209	90
3a. Address P.O. Box 2197, DU 30 Houston, TX 77252-2	2197	3b. Phone No. (include area cod (281) 293-1613	e) 20% (7)	10. Field And Pool, Or 8 BLANCO P	Exploratory Area ICTURED CLIFFS
Location Of Well (Footage, Sec.     2090' FSL - 1830'	11. County Or Parish, State RIO ARRIBA COUNTY, NM				
	CK APPROPRIATE	BOX(ES) TO INDICATE NA	TURE OF NOTICE, REF	PORT, OR OTHER D	ATA
TYPE OF SUBMISSION			TYPE OF ACTION		
Notice of Intent  Subsequent Report  Final Abandonment Notice  Acidize  Alter Casing  Casing Repa		ir New Constru	Fracture Treat Reclamation  New Construction Recomplete  Plug and Abandon Temporarily Abandon		Water Shut-off Well Integrity Other:
3 Describe Brancad as Complete	10				

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which work will be performed or provide the Bond No. on rile with the BLMBIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or Recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

PLEASE SEE REVERSE SIDE FOR COMPLETION DETAILS ON THE BLANCO PICTURED CLIFFS FORMATION. THE PC IS PRODUCED UP THRU THE CASING, THE DK IS PRODUCED THRU THE TUBING.

14. I hereby certify that the foregoing is true and correct Name (Printed / Typed):  DEBRA SITTNER	itle Agent fo	or Conoco Inc.		
Signature Signatures .	Date 12/20/	00		
THIS SPACE FOR FEDER	AL OR STATE	OFFICE USE		
Approved by	Title	Date		
Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	Office OFFI		
Ti le 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and st itements or representations as to any matter within its jurisdiction.	wilfully to make to any	department or agency of the thes Sales are life fictitious or fraudulent		
*SOCIALS		1 Smm - orrice		
Ki JOBS CCNCCO(1142-A (11SJ) 28-7-290's 228-PC-Sub data		×		

SAN JUAN 28-7 UNIT 228 (SSM 11/1/2000) PC RECOMPLE					MPLETION			
			ly Summar	У				
300392099000		1	RIO ARRIBA	NEW MEXICO	Operator		_03'85 *v2	
-43 Bev. *: 6816.00	3rant Eer 1: 6804.00	43-0月년 6816.00	#D-Tuting Head Distance ( 6816.00	ti Frug Back Total Beern	<b>*</b> 21	Sout Circ 9/3/74	Rig Flee Be Dire	
Star!	7		, Z ¥					
	Cos This Ret  HELD SAFETY MEETING, MIRU, CSG PRESSURE 200 #, TBG PRESSURE 180 #, KILLED WELL, NDWH - NUBOP, RIH							
	TAGGED FOR FILL. NO FILL. TAGGED @ 7799', POOH W/2 3/8" TBG. SWION.							
	HELD SAFETY MEETING. CSG PRESSURE 50 #. BLEED WELL DOWN. RIH W/41/2" RBP ON 23/8" TBG. SET @ 3900'. PRESSURE TESTED CSG TO 3000 #. HELD OK. POOH W/23/8" TBG. SWION.							
11/3/00	HELD SAFETY MEE	TING. RU SCHLUMBER				000'. RAN GA	MMA RAY & CCL	
	FROM 3900' TO SU	IRFACE, SWION,						
11/6/00	HELD SAFETY MEETING. RU BLUE JET. PERFORATED THE PICTURED CLIFFS. RIH W/ 3 1/8" 90 DEGREE PP SLECT FIRE PERFORATING GUN. PERFORATED FROM 3336' - 3362', 3370' - 3382', 3400' - 3418'. TOTAL OF 50 HOLES. 0 # PRESSURE AFTER PERFORATING. RD BLUE JET. SWION.							
11/7/00	STAND BY TIME. V	VATING ON FRAC						
11/8/00 11/9/00	STAND BY TIME. V							
	STAND BY TIME. V STAND BY TIME. V							
11/13/00		TING. RU HOT OILER.	HEATED WATER IN F	RAC TANKS.				
11/14/00	HELD SAFETY MEE	TING. RU HALLIBURTO	N. FOAM FRAC THE	PICTURED CLIFFS	. TESTED F	RAC LINES T	O 5000 #. HELD	
	OK. BROKE WELL BALLED OFF @ 32	DOWN @ 2567 # @ 17 168 #. SHUT DOWN. RI # LINEAR & 508,100 SO	BPM. DROPPED 70 U BLUE JET. RIH W/	BALL SEALERS @ JUNK BASKET TO	1 BALL PE 3890', RET	R BBL. GOO! REVED BALL	DBALL ACTION. SEALERS. FOAM	
	AVG PRESSURE 2	181 #. ISIP 1228 #. 5 M	IN 1177 #. FRAC GF	AIDENT .48. SVVIC	N.	71 3AND. AY	OTALL 43 DEMI.	
11/15/00	HELD SAFETY MEE	TING. INSTALLED DRIL	L GAS COMPRESSO	RS.				
	THROUGH 1/2" CH	TING. INSTALLED DRIL OKE @ 300 #. WELL M 12 BBLS WATER AND	AKING 3 BBL OF WA	TER PER HR AND	RE 800 # . I A TRACE C	FLOWED WEL OF SAND. FLO	L TO PIT DWED WELL 4	
11/17/00	HELD SAFETY MEE	TING. CSG PRESSURE NED OUT FROM 3364' TO	750 #. KILLED WEL	L. RIH VV/ 2 3/8" VV	ORK STRING	G. TAGGED S	AND @ 3364'. RU	
	STRING. TESTED T BWPD. WITNESSEI TO RBP - POOH WI 3460' BETWEEN DA	J DRILL GAS - CLEANEI HE PICTURED CLIFF UP D BY NOE PARRA & SA I RBP & 2 3/8" WORK ST AKOTA & PICTURED CLII AKOTA THRU 2 3/8" TE	4 1/2" CSG FROM 3: M MCFADDEN. RIH ' RING. RIH W/ 4 1/2" FF. END OF TBG @	370' THRU 1/2" CHK N/ ON & OFF TOOI LOCK-SET PRODU 7696' - SEAT NIPPU	OKE @ 300 L ON 2 3/8* JCTION PKR LE @ 7696'	#. 1850 MCF WORK STRIN 8 & 2 3/8" TBG TO 7697' - ML	PD, 1 BOPD, 5 G. LATCHED ON . SET PKR @	
WellView®			Page 1		R	leport gener	ated on 11/20/00	