5. LEASE NOO-C-14-20-7477

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEL OR TRIBE NAME
	NAVAJO , FIFT & OLAVAN
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME 22
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME 및 실종을
1. oil gas X other	DOME NAVAJO 13-26-13 STE
well well other	9. WELL NO. 원교 등을 원 기를 들었다.
2. NAME OF OPERATOR	2 # 3 3 4 3 2
DOME PETROLEUM CORPORATION	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR 501 Airport Drive	WAW FRUITLAND-PICTURED CLIFF
Suite 107, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	1 문항상암 및 경우없다
below.) AT SURFACE: 1520' FNL, 1850' FEL	Sec. 13, T26N, R13W 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
AT TOP PROD. INTERVAL:	[ 김주환집] - 김 후, 취류
AT TOTAL DEPTH:	SAN JUAN
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	[중요] 지수호로입
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6013 GR (\$ 8.5 - 19 8.5 5 5 7 )
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	1018 7 7 8
TEST WATER SHUT-OFF	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
FRACTURE TREAT	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING [	change on Form 9-330.) -
MULTIPLE COMPLETE	그 그는 그는 이 그 첫째 회원 이 유기회 공속 회사 중
CHANGE ZONES	그 그 그 그 중에 가고 그 그 그 한 지하는데 요즘 없는데 없다.
(other) SPUD & SET SURFACE CASING.	
<ol> <li>DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d</li> </ol>	e all pertinent details, and give pertinent dates,
measured and true vertical depths for all markers and zones pertiner	it to this work.)*
	그 불월이 힘이 하는 기원 수용
Spudded 8 3/4" hole at 12:30 PM, 12/13/79. I	Orilled to 110 . Ran 3 joints
(107') 5 1/2", 15.5#, K-55 LT&C casing. Cas	
with 35 sacks class "B" cement with 2% CaCl.	Plug down at 6:00 PM, \$2/13/79
Circulated cement EIVED	유혈 불합합 - 기 기 회 경험
	프로그는 발생활동을 하면 함께 무립성을 하다.
5701977	
· · · · · · · · · · · · · · · · · · ·	
CAPACGICAL SURVEY	
YANNINGTON, N. M.	
	7.34 (0.70)
	DEDZ
	Tour tong to the Line
Subsurface Safety Valve: Manu. and Type	DISI 3
18. I hereby certify that the foregoing is true and correct	
SIGNED TITLDRLG & PROD FO	REMAN DATE December 17, 1979
(This space for Federal or State of	fice use)
APPROVED BY TITLE	DATEDATE
CONDITIONS OF APPROVAL, IF ANY:	
	· · · · · · · · · · · ·
NMOCC*	
	oras A Bis

\*See Instructions on Reverse Side

E. 3