Maralex Resources, Inc. 518 17th St., Suite 1030 Denver, Colorado 80202

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- 1. 11 Marron W. N. Fed Com. Sec. 24, T. 27 N., R. 8 W., San Juan County. New Mexico, lease NM-03605-A.
- 2. 12 Marron W. N. Fed Com, Sec. 27, T. 27 N., R. 8 W., San Juan County, New Mexico, lease NM-03604.
- 3. 9 Oxnard W. N. Federal, Sec. 13, T. 27 N., R. 8 W., San Juan County, New Mexico, lease SF-078476.

The subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

Ken Townsend

OIL CON. DIV. FOR John L. Keller Chief, Branch of Mineral Resources

JUN1 8 1992

3 Enclosures

cc: NMOCD, Aztec. NM

ABANDONED LOCATION