Budget Bureau No. 42-R358.4. Approval expires 12-31-60. Form 9-331 a (Feb. 1951) Land Office (SUBMIT IN TRIPLICATE) - File UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS ON WELLS SUBSEQUENT REPORT OF WATER SHUT-OFF ... NOTICE OF INTENTION TO DRILL. SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING. NOTICE OF INTENTION TO CHANGE PLANS... SUBSEQUENT REPORT OF ALTERING CASING..... NOTICE OF INTENTION TO TEST WATER SHUT-OFF..... SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR. NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL..... SUBSEQUENT REPORT OF ABANDONMENT..... NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... SUPPLEMENTARY WELL HISTORY..... NOTICE OF INTENTION TO PULL OR ALTER CASING NOTICE OF INTENTION TO ABANDON WELL. (INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA) February 21, is located 1730 ft. from ${\mathbb{F}}$ line and 1730 ft. from ${\mathbb{F}}$ line of sec. 33 E.A.P.M. 26 Korth MR/A SW/A Sec. 33 (Meridian) (Twp.) (Range) (1/4 Sec. and Sec. No.) Rio Attiba neo Musa Yard (State or Territory) (County or Subdivision) (Field) The elevation of the derrick moor above sea level is ft. DETAILS OF WORK (State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work) Set 198.36' of 10-3/4" ensing # 203.58', cemented with 200 ax w/25 CaCl. Set 3654.80' of 7-5/8" oneing # 3666', commuted w/150 am 86 gal & 50 am ment. Set 2283.05' of 5-1/2" liner 6 5846.29' on Beach Rose liner hanger 6 3563.24' commuted v/150 az reg. Squeezed top liner u/46 az u/250f.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations.

PACIFIC NUMBERS PIPELIES CONFORMATION

OIST, 3

Address

Paradagten, New Musico

By

Title