
(November 1983) (Formerly 9–331)	UNITED STATES PARTMENT OF THE INTE BUREAU OF LAND MANAGEME	RIOR (Other instructions on r	Budget Bureau Expires August 5. LEASE DESIGNATION 240	No. 1004-0135
SUNDRY (Do not use this form i	NOTICES AND REPORTS or proposals to drill or to deepen or plus 'APPLICATION FOR PERMIT—" for suc	S ON WELLS ug back to a different reservoir. th proposals.)	6. IF INDIAN, ALLOTTE	E OR TRIBE NAME
OIL GAS XX OTHER			7. UNIT AGREEMENT NAME Jicarilla Apache 240	
2. NAME OF OPERATOR Holcomb Oil & Gas, 3. ADDRESS OF OPERATOR	Inc.		8. FARM OR LEASE WAY	(B
P.O. Box 2058, Farmington, NM 87499 1. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* At surface 660 FNL x 2310 FEL 14. PERMIT NO 15. ELEVATIONS (Show whether DF, RT, OR, etc.)			9. WBLL NO. 2 10. FIBLD AND POOL, OR WILDCAT BOULder Mancos 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA Sec. 26 T28N R1W	
	eck Appropriate Box To Indicate of Intention to:		Other Data	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL **(Other) WORK OV	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report result	of multiple completion on Well etion Report and Log form.) Including estimated date of starting any I depths for all markers and sones perti-	

1. Prep location.

- 2. Run wireline capacitance tool and GR and CCL to determine downhole equipment and fluid level.
- 3. Swab test as necessary.
- 4. Evaluate above testing to determine further action.



*See Instructions on Reverse Side