

## OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil &amp; Gas Lease No.

Fee

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)OIL WELL ☐ GAS WELL ☒ OTHER ☐

Name of Operator

El Paso Natural Gas Company

Address of Operator

P.O. Box 4289, Farmington, New Mexico 87499-4289

Location of well

UNIT LETTER G 1650' FEET FROM THE N LINE AND 1550' FEET FROMTHE East LINE, SECTION 33 TOWNSHIP 28 RANGE 5 NMPM.

7. Unit Agreement Name

San Juan 28-5 Unit

8. Farm or Lease Name

9. Well No.

#52

10. Field and Pool, or Wildcat

Blanco MV

15. Elevation (Show whether DF, RT, GR, etc.)

6601 GL

12. County

Rio Arriba

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐PLUG AND ABANDON ☐CHANGE PLANS ☐OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-30-85: MOL & RU. Spot 30 sx cement plug to cover 60' above Mesa Verde Perfs.  
Displace w/ 9# gal. gel.5-31-85: Tag cement at 5715'. Spot 30 sx cement plug to cover 60' above Mesa Verde  
perfs. Mesa Verde on vacuum. WOC 6 hours. Tag cement at 5715'. Spot 40 sx  
cement plug WOC.6-3-85: Tag plug at 4986'. Cut casing at 3672'. Spot 25 sx plug to cover casing stub  
and Int. casing shoe. Spot 25 sx plug (3478'-3378') to cover 50' above PC  
formation.6-4-85: Shot holes in casing at 205'. Establish circ. circulate cement to surface.  
Cut off casing below ground level. Erect surface marker. RD & MOL.RECEIVED  
JUN 12 1985OIL CON. DIV.  
DIST. 3

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Barry A. Whelan TITLE Production EngineerDATE 6-6-85

Original Signed by CHARLES GHOLSON

DEPUTY OIL &amp; GAS INSPECTOR, DIST. #3

APR 09 1986

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: